

# Vehicle Inspection Report

Report no.: MC-IR-50684 | Vehicle ID: 50684 | Datum vystavení: 2026-06-10

LISTING <b>2026 Suzuki Hayabusa GSX - R 1300 Demo Fahrzeug in Menden be</b>	TYP Motorcycle	STAV available
MAKE Suzuki	MODEL Hayabusa	ROK 2026
STAV used	LOCATION Denmark	WARRANTY INFORMATION Inspection available before handover

<b>100%</b> Dealer reviewed inventory	<b>Review</b> Dealer certification	<b>Prepared</b> Handover preparation
--	---------------------------------------	---

## IDENTITY AND DOCUMENTATION

CHECKPOINT	FINDING / NOTE	RESULT
Vehicle ID	50684	VERIFIED
Vehicle type	Motorcycle	VERIFIED
VIN / chassis number	To be confirmed at handover	PENDING
Registration date	Not supplied	PENDING
Original registration papers	Available for dealer handover review	VERIFIED

## MECHANICAL INSPECTION

CHECKPOINT	FINDING / NOTE	RESULT
Engine start and idle	Cold start, idle stability and visible leak check	PASSED
Engine size	1.340 cm <sup>3</sup>	VERIFIED
Transmission	Schaltgetriebe	VERIFIED
Powertrain response	Throttle response, clutch/drive engagement and abnormal noise check	PASSED
Cooling and fluids	Oil, coolant, brake fluid and visible hose condition checked	PASSED

## SAFETY AND ROADWORTHINESS

CHECKPOINT	FINDING / NOTE	RESULT
Brakes	Front/rear braking response and visible disc/pad condition checked	PASSED
Tyres / wheels	Tyre condition, wheel alignment indicators and visible rim damage checked	PASSED
Suspension / steering	Steering movement, fork/shock condition and bearing play check	PASSED
Lights / horn / controls	Operational control check completed	PASSED
Mileage	10	RECORDED

## COSMETIC AND PREPARATION

CHECKPOINT	FINDING / NOTE	RESULT
Exterior color	Not specified	PENDING
Body panels / frame	Visible condition and preparation notes reviewed	PASSED
Dealer preparation	Prepared before customer handover	VERIFIED
Dealer certification	Dealer review required before final handover	PENDING

## DELIVERY READINESS

CHECKPOINT	FINDING / NOTE	RESULT
Pickup readiness	Customer pickup can be scheduled after admin confirmation	READY
Road delivery	Covered or trailer delivery can be arranged where available	AVAILABLE
International delivery	International export support available	AVAILABLE
Handover documents	Contract, invoice and inspection report prepared for customer review	READY

## LISTING EQUIPMENT AND NOTES

Make: Suzuki Model: Hayabusa Version: GSX - R 1300 Demo Fahrzeug in Menden be Body type: Supersport Condition: Used  
Mileage: 10 km Engine: 1.340 cm<sup>3</sup> Power: 140 kW (190 PS) Fuel: Benzin Transmission: Schaltgetriebe

## INSPECTOR / HANDOVER SIGN-OFF

PREPARED BY MotoComply ApS inspection team	FINAL HANDOVER CONFIRMATION _____
---	--------------------------------------