PROFESSIONEL INSPEKTIONSRAPPORT

Inspektionsrapport for båd / yacht

MotoComply ApS
CVR 46320565
0045 98 89 89 98
info@motocomplydk.com

Rapportnr.: MC-IR-53790 | Køretøjs-ID: 53790 | Udstedelsesdato: 2026-10-30

ANNONCE	TYPE	STATUS
2023 Delta Powerboats 33 Coupe	Båd	Tilgængelig
BYGGER / MÆRKE	**MODEL**	**ÅRGANG**
Delta	Powerboats 33 Coupe	2023
STAND	**PLACERING**	**GARANTIINFORMATION**
Brugt	European marina network	Inspection available before handover

100%	Review	Prepared
Dealer reviewed inventory	Dealer certification	Handover preparation

VESSEL IDENTITY AND TITLE REVIEW

KONTROLPUNKT	FUND / NOTE	RESULTAT
Køretøjs-ID	53790	VERIFICERET
Vessel type	Båd	VERIFICERET
Bygger / mærke	Delta	VERIFICERET
Hull identification / registration number	Bekræftes ved overdragelse	AFVENTER
Original registration papers	Available for dealer handover review	VERIFICERET

HULL, DECK AND EXTERIOR SURVEY

KONTROLPUNKT	FUND / NOTE	RESULTAT
Hull material	Ikke specificeret	AFVENTER
Hull visual inspection	Visible hull, gelcoat/paint and impact indicators reviewed	BESTÅET
Deck fittings and rails	Visible deck fittings, rails, cleats and access points checked	BESTÅET
Length / beam / draft	- / - / -	REGISTRERET
Current marina / location	European marina network	REGISTRERET

ENGINE, PROPULSION AND SYSTEMS

KONTROLPUNKT	FUND / NOTE	RESULTAT
Engine type	Ikke specificeret	AFVENTER
Engine power	Ikke specificeret	AFVENTER
Engine hours	Ikke specificeret	AFVENTER
Fuel type	Ikke specificeret	AFVENTER
Visible engine bay review	Leaks, corrosion indicators, belts, hoses and accessible systems reviewed	BESTÅET

ACCOMMODATION AND ONBOARD EQUIPMENT

KONTROLPUNKT	FUND / NOTE	RESULTAT
Cabins	Ikke specificeret	AFVENTER
Berths	Ikke specificeret	AFVENTER
Water capacity	Ikke specificeret	AFVENTER
Fuel capacity	Ikke specificeret	AFVENTER
Included equipment	Year: 2023 Electrical Equipment Shore Power Inlet: ✓ Generator: ✓ Electronics Depthsounder: ✓ Radar: ✓ Radar Detector: ✓ Navigation Center: ✓ Autopilot: ✓ Radio: ✓ Compass: ✓ GPS: ✓ Cockpit Speakers: ✓ VHF: ✓ AIS: ✓ Inside Equipment Bow Thruster: ✓ Electric Bilge Pump: ✓ Manual Bilge Pump: ✓ Air Conditioning: ✓ Electric Head: ✓ Heating: ✓ Refrigerator: ✓ Battery Charger: ✓ Outside Equipment Cockpit Shower: ✓ Electric Winch: ✓ Cockpit Cushions: ✓ Cockpit Table: ✓ Swimming Ladder: ✓ Gyroscopic Stabilizer: ✓	GENNEMGÅET

MARINE DELIVERY AND EXPORT READINESS

KONTROLPUNKT	FUND / NOTE	RESULTAT
Port delivery	Destination port delivery can be arranged where available	TILGÆNGELIG
Export support	Export eligible listing	KLAR
Insurance handover note	Carrier/port handover should be documented before dispatch	PÅKRÆVET
Survey note	Marine survey scope recorded for customer handover	BEMÆRKNING

LISTING EQUIPMENT AND NOTES

Year: 2023 Electrical Equipment Shore Power Inlet: ✓ Generator: ✓ Electronics Depthsounder: ✓ Radar: ✓ Radar Detector: ✓ Navigation Center: ✓ Autopilot: ✓ Radio: ✓ Compass: ✓ GPS: ✓ Cockpit Speakers: ✓ VHF: ✓ AIS: ✓ Inside Equipment Bow Thruster: ✓ Electric Bilge Pump: ✓ Manual Bilge Pump: ✓ Air Conditioning: ✓ Electric Head: ✓ Heating: ✓ Refrigerator: ✓ Battery Charger: ✓ Outside Equipment Cockpit Shower: ✓ Electric Winch: ✓ Cockpit Cushions: ✓ Cockpit Table: ✓ Swimming Ladder: ✓ Gyroscopic Stabilizer: ✓

INSPECTOR / HANDOVER SIGN-OFF

PREPARED BY	FINAL HANDOVER CONFIRMATION
MotoComply ApS inspection team	_____