PROFESSIONEL INSPEKTIONSRAPPORT

# Inspektionsrapport for båd / yacht

**MotoComply ApS**
CVR 46320565
0045 98 89 89 98
info@motocomplydk.com

Rapportnr.: MC-IR-66066 | Køretøjs-ID: 66066 | Udstedelsesdato: 2026-10-30

| ANNONCE | TYPE | STATUS |
|---|---|---|
| **2026 Wellcraft 44 Explorer** | Båd | Tilgængelig |
| BYGGER / MÆRKE | MODEL | ÅRGANG |
| Wellcraft | 44 Explorer | 2026 |
| STAND | PLACERING | GARANTIINFORMATION |
| Brugt | European marina network | Inspection available before handover |

| 100% | Review | Prepared |
|---|---|---|
| Dealer reviewed inventory | Dealer certification | Handover preparation |

## VESSEL IDENTITY AND TITLE REVIEW

| KONTROLPUNKT | FUND / NOTE | RESULTAT |
|---|---|---|
| **Køretøjs-ID** | 66066 | VERIFICERET |
| **Vessel type** | Båd | VERIFICERET |
| **Bygger / mærke** | Wellcraft | VERIFICERET |
| **Hull identification / registration number** | Bekræftes ved overdragelse | AFVENTER |
| **Original registration papers** | Available for dealer handover review | VERIFICERET |

## HULL, DECK AND EXTERIOR SURVEY

| KONTROLPUNKT | FUND / NOTE | RESULTAT |
|---|---|---|
| **Hull material** | Ikke specificeret | AFVENTER |
| **Hull visual inspection** | Visible hull, gelcoat/paint and impact indicators reviewed | BESTÅET |
| **Deck fittings and rails** | Visible deck fittings, rails, cleats and access points checked | BESTÅET |
| **Length / beam / draft** | - / - / - | REGISTRERET |
| **Current marina / location** | European marina network | REGISTRERET |

## ENGINE, PROPULSION AND SYSTEMS

| KONTROLPUNKT | FUND / NOTE | RESULTAT |
|---|---|---|
| **Engine type** | Ikke specificeret | AFVENTER |
| **Engine power** | Ikke specificeret | AFVENTER |
| **Engine hours** | Ikke specificeret | AFVENTER |
| **Fuel type** | Ikke specificeret | AFVENTER |
| **Visible engine bay review** | Leaks, corrosion indicators, belts, hoses and accessible systems reviewed | BESTÅET |

## ACCOMMODATION AND ONBOARD EQUIPMENT

| KONTROLPUNKT | FUND / NOTE | RESULTAT |
|---|---|---|
| **Cabins** | Ikke specificeret | AFVENTER |
| **Berths** | Ikke specificeret | AFVENTER |
| **Water capacity** | Ikke specificeret | AFVENTER |
| **Fuel capacity** | Ikke specificeret | AFVENTER |
| **Included equipment** | Year: 2026 | GENNEMGÅET |

## MARINE DELIVERY AND EXPORT READINESS

| KONTROLPUNKT | FUND / NOTE | RESULTAT |
|---|---|---|
| **Port delivery** | Destination port delivery can be arranged where available | TILGÆNGELIG |
| **Export support** | Export eligible listing | KLAR |
| **Insurance handover note** | Carrier/port handover should be documented before dispatch | PÅKRÆVET |
| **Survey note** | Marine survey scope recorded for customer handover | BEMÆRKNING |

## LISTING EQUIPMENT AND NOTES

Year: 2026

## INSPECTOR / HANDOVER SIGN-OFF

| PREPARED BY | FINAL HANDOVER CONFIRMATION |
| --- | --- |
| MotoComply ApS inspection team | _____ |