PROFESSIONEL INSPEKTIONSRAPPORT

Inspektionsrapport for køretøj

MotoComply ApS
CVR 46320565
0045 98 89 89 98
info@motocomplydk.com

Rapportnr.: MC-IR-50684 | Køretøjs-ID: 50684 | Udstedelsesdato: 2026-10-31

ANNONCE	TYPE	STATUS
2026 Suzuki Hayabusa GSX - R 1300 Demo Fahrzeug in Menden be	Motorcykel	Tilgængelig

MÆRKE	MODEL	ÅRGANG
Suzuki	Hayabusa	2026

STAND	PLACERING	GARANTIINFORMATION
Brugt	Denmark	Inspection available before handover

100%	Review	Prepared
Dealer reviewed inventory	Dealer certification	Handover preparation

IDENTITET OG DOKUMENTATION

KONTROLPUNKT	FUND / NOTE	RESULTAT
Køretøjs-ID	50684	VERIFICERET
Køretøjstype	Motorcykel	VERIFICERET
VIN / stelnummer	Bekræftes ved overdragelse	AFVENTER
Registreringsdato	Ikke angivet	AFVENTER
Original registration papers	Available for dealer handover review	VERIFICERET

MEKANISK INSPEKTION

KONTROLPUNKT	FUND / NOTE	RESULTAT
Engine start and idle	Cold start, idle stability and visible leak check	BESTÅET
Engine size	1.340 cm³	VERIFICERET
Transmission	inspection_report.value_transmission_Schaltgetriebe	VERIFICERET
Powertrain response	Throttle response, clutch/drive engagement and abnormal noise check	BESTÅET
Cooling and fluids	Oil, coolant, brake fluid and visible hose condition checked	BESTÅET

SIKKERHED OG KØREKLARHED

KONTROLPUNKT	FUND / NOTE	RESULTAT
Brakes	Front/rear braking response and visible disc/pad condition checked	BESTÅET
Tyres / wheels	Tyre condition, wheel alignment indicators and visible rim damage checked	BESTÅET
Suspension / steering	Steering movement, fork/shock condition and bearing play check	BESTÅET
Lights / horn / controls	Operational control check completed	BESTÅET
Mileage	10	REGISTRERET

KOSMETIK OG KLARGØRING

KONTROLPUNKT	FUND / NOTE	RESULTAT
Exterior color	Ikke specificeret	AFVENTER
Body panels / frame	Visible condition and preparation notes reviewed	BESTÅET
Dealer preparation	Prepared before customer handover	VERIFICERET
Dealer certification	Dealer review required before final handover	AFVENTER

LEVERINGSKLARHED

KONTROLPUNKT	FUND / NOTE	RESULTAT
Pickup readiness	Customer pickup can be scheduled after admin confirmation	KLAR
Road delivery	Covered or trailer delivery can be arranged where available	TILGÆNGELIG
International delivery	International export support available	TILGÆNGELIG
Handover documents	Contract, invoice and inspection report prepared for customer review	KLAR

LISTING EQUIPMENT AND NOTES

Make: Suzuki Model: Hayabusa Version: GSX - R 1300 Demo Fahrzeug in Menden be Body type: Supersport Condition: Used Mileage: 10 km Engine: 1.340 cm³ Power: 140 kW (190 PS) Fuel: Benzin Transmission: Schaltgetriebe

INSPECTOR / HANDOVER SIGN-OFF

PREPARED BY	FINAL HANDOVER CONFIRMATION
MotoComply ApS inspection team	_____