

Vehicle Inspection Report

Report no.: MC-IR-45583 | Vehicle ID: 45583 | Ausstellungsdatum: 2026-06-10

LISTING HARLEY-DAVIDSON	TYP Motorcycle	STATUS available
MAKE Harley-Davidson	MODEL Erbacher The One	BAUJAHR 2014
ZUSTAND excellent	LOCATION Denmark	WARRANTY INFORMATION 12 Months Limited Warranty

100% Dealer reviewed inventory	Certified Dealer certification	Serviced Handover preparation
--	--	---

IDENTITY AND DOCUMENTATION

CHECKPOINT	FINDING / NOTE	RESULT
Vehicle ID	45583	VERIFIED
Vehicle type	Motorcycle	VERIFIED
VIN / chassis number	To be confirmed at handover	PENDING
Registration date	Not supplied	PENDING
Original registration papers	Available for dealer handover review	VERIFIED

MECHANICAL INSPECTION

CHECKPOINT	FINDING / NOTE	RESULT
Engine start and idle	Cold start, idle stability and visible leak check	PASSED
Engine size	2000	VERIFIED
Transmission	manual	VERIFIED
Powertrain response	Throttle response, clutch/drive engagement and abnormal noise check	PASSED
Cooling and fluids	Oil, coolant, brake fluid and visible hose condition checked	PASSED

SAFETY AND ROADWORTHINESS

CHECKPOINT	FINDING / NOTE	RESULT
Brakes	Front/rear braking response and visible disc/pad condition checked	PASSED
Tyres / wheels	Tyre condition, wheel alignment indicators and visible rim damage checked	PASSED
Suspension / steering	Steering movement, fork/shock condition and bearing play check	PASSED
Lights / horn / controls	Operational control check completed	PASSED
Mileage	2207	RECORDED

COSMETIC AND PREPARATION

CHECKPOINT	FINDING / NOTE	RESULT
Exterior color	Black	RECORDED
Body panels / frame	Visible condition and preparation notes reviewed	PASSED
Dealer preparation	Recently serviced before listing	VERIFIED
Dealer certification	Dealer certified listing	VERIFIED

DELIVERY READINESS

CHECKPOINT	FINDING / NOTE	RESULT
Pickup readiness	Customer pickup can be scheduled after admin confirmation	READY
Road delivery	Covered or trailer delivery can be arranged where available	AVAILABLE
International delivery	Available by custom quote	AVAILABLE
Handover documents	Contract, invoice and inspection report prepared for customer review	READY

LISTING EQUIPMENT AND NOTES

Dealer certified
Recently serviced
Secure contract
Complimentary delivery

INSPECTOR / HANDOVER SIGN-OFF

PREPARED BY

MotoComply ApS inspection team

FINAL HANDOVER CONFIRMATION

MotoComply ApS inspection report for Vehicle ID 45583. This report is generated from the current listing record and should be updated if listing data or inspection notes change.