

Vehicle Inspection Report

Report no.: MC-IR-28256 | Vehicle ID: 28256 | Ausstellungsdatum: 2026-06-13

| | | |
|-------------------------------------------|---------------------|--------------------------------------------------------------|
| LISTING 2023 Indian Scout Rogue | TYP Motorcycle | STATUS available |
| MAKE Indian | MODEL Scout | BAUJAHR 2023 |
| ZUSTAND used | LOCATION Denmark | WARRANTY INFORMATION Inspection available before handover |

| | | |
|------------------------------------------|---------------------------------------|-----------------------------------------|
| 100% Dealer reviewed inventory | Review Dealer certification | Prepared Handover preparation |
|------------------------------------------|---------------------------------------|-----------------------------------------|

IDENTITY AND DOCUMENTATION

| CHECKPOINT | FINDING / NOTE | RESULT |
|------------------------------|--------------------------------------|----------|
| Vehicle ID | 28256 | VERIFIED |
| Vehicle type | Motorcycle | VERIFIED |
| VIN / chassis number | To be confirmed at handover | PENDING |
| Registration date | 2023-06-01 | REVIEWED |
| Original registration papers | Available for dealer handover review | VERIFIED |

MECHANICAL INSPECTION

| CHECKPOINT | FINDING / NOTE | RESULT |
|-----------------------|---------------------------------------------------------------------|----------|
| Engine start and idle | Cold start, idle stability and visible leak check | PASSED |
| Engine size | 1.133 cm ³ | VERIFIED |
| Transmission | Schaltgetriebe | VERIFIED |
| Powertrain response | Throttle response, clutch/drive engagement and abnormal noise check | PASSED |
| Cooling and fluids | Oil, coolant, brake fluid and visible hose condition checked | PASSED |

SAFETY AND ROADWORTHINESS

| CHECKPOINT | FINDING / NOTE | RESULT |
|--------------------------|---------------------------------------------------------------------------|----------|
| Brakes | Front/rear braking response and visible disc/pad condition checked | PASSED |
| Tyres / wheels | Tyre condition, wheel alignment indicators and visible rim damage checked | PASSED |
| Suspension / steering | Steering movement, fork/shock condition and bearing play check | PASSED |
| Lights / horn / controls | Operational control check completed | PASSED |
| Mileage | 10570 | RECORDED |

COSMETIC AND PREPARATION

| CHECKPOINT | FINDING / NOTE | RESULT |
|----------------------|--------------------------------------------------|----------|
| Exterior color | Not specified | PENDING |
| Body panels / frame | Visible condition and preparation notes reviewed | PASSED |
| Dealer preparation | Prepared before customer handover | VERIFIED |
| Dealer certification | Dealer review required before final handover | PENDING |

DELIVERY READINESS

| CHECKPOINT | FINDING / NOTE | RESULT |
|------------------------|----------------------------------------------------------------------|-----------|
| Pickup readiness | Customer pickup can be scheduled after admin confirmation | READY |
| Road delivery | Covered or trailer delivery can be arranged where available | AVAILABLE |
| International delivery | International export support available | AVAILABLE |
| Handover documents | Contract, invoice and inspection report prepared for customer review | READY |

LISTING EQUIPMENT AND NOTES

Make: Indian Model: Scout Version: Rogue Body type: Motorbike Condition: Used First registration: 06/2023 Mileage: 10.570 km
Engine: 1.133 cm³ Power: 69 kW (94 PS) Fuel: Benzin Transmission: Schaltgetriebe

INSPECTOR / HANDOVER SIGN-OFF

| | |
|-----------------------------------------------|--------------------------------------|
| PREPARED BY MotoComply ApS inspection team | FINAL HANDOVER CONFIRMATION _____ |
|-----------------------------------------------|--------------------------------------|