

# Marine / Yacht Inspection Report

Report no.: MC-IR-93298 | Vehicle ID: 93298 | Issue date: 2026-06-10

|                                  |                                     |  |
|----------------------------------|-------------------------------------|--|
| LISTING<br><b>2010 Hanse 545</b> | TYPE<br>Boat                        | STATUS<br>available  |
| BUILDER / MAKE<br>Hanse          | MODEL<br>545                        | YEAR<br>2010   |
| CONDITION<br>used                | LOCATION<br>European marina network | WARRANTY INFORMATION<br>Inspection available before handover |

|  |                                       |   |
|--|---------------------------------------|---|
| <b>100%</b><br>Dealer reviewed inventory | <b>Review</b><br>Dealer certification | <b>Prepared</b><br>Handover preparation |
|--|---------------------------------------|---|

## VESSEL IDENTITY AND TITLE REVIEW

| CHECKPOINT                                | FINDING / NOTE                       | RESULT   |
|---|--------------------------------------|----------|
| Vehicle ID                                | 93298                                | VERIFIED |
| Vessel type                               | Boat                                 | VERIFIED |
| Builder / make                            | Hanse                                | VERIFIED |
| Hull identification / registration number | To be confirmed at handover          | PENDING  |
| Original registration papers              | Available for dealer handover review | VERIFIED |

## HULL, DECK AND EXTERIOR SURVEY

| CHECKPOINT                | FINDING / NOTE   | RESULT   |
|---------------------------|--|----------|
| Hull material             | Not specified  | PENDING  |
| Hull visual inspection    | Visible hull, gelcoat/paint and impact indicators reviewed     | PASSED   |
| Deck fittings and rails   | Visible deck fittings, rails, cleats and access points checked | PASSED   |
| Length / beam / draft     | - / - / -  | RECORDED |
| Current marina / location | European marina network  | RECORDED |

## ENGINE, PROPULSION AND SYSTEMS

| CHECKPOINT                | FINDING / NOTE  | RESULT  |
|---------------------------|---|---------|
| Engine type               | Not specified   | PENDING |
| Engine power              | Not specified   | PENDING |
| Engine hours              | Not specified   | PENDING |
| Fuel type                 | Not specified   | PENDING |
| Visible engine bay review | Leaks, corrosion indicators, belts, hoses and accessible systems reviewed | PASSED  |

## ACCOMMODATION AND ONBOARD EQUIPMENT

| CHECKPOINT         | FINDING / NOTE   | RESULT   |
|--------------------|--|----------|
| Cabins             | Not specified  | PENDING  |
| Berths             | Not specified  | PENDING  |
| Water capacity     | Not specified  | PENDING  |
| Fuel capacity      | Not specified  | PENDING  |
| Included equipment | Year: 2010 Electronics Depthsounder: ✓ Radar: ✓ Log-Speedometer: ✓ Wind Speed and Direction: ✓ Navigation Center: ✓ Plotter: ✓ Autopilot: ✓ Radio: ✓ Compass: ✓ CD Player: ✓ VHF: ✓ Flat Screen TV: ✓ AIS: ✓ | REVIEWED |

## MARINE DELIVERY AND EXPORT READINESS

| CHECKPOINT              | FINDING / NOTE   | RESULT    |
|-------------------------|--|-----------|
| Port delivery           | Destination port delivery can be arranged where available  | AVAILABLE |
| Export support          | Export eligible listing                                    | READY     |
| Insurance handover note | Carrier/port handover should be documented before dispatch | REQUIRED  |
| Survey note             | Marine survey scope recorded for customer handover         | ADVISORY  |

## LISTING EQUIPMENT AND NOTES

Year: 2010 Electronics Depthsounder: ✓ Radar: ✓ Log-Speedometer: ✓ Wind Speed and Direction: ✓ Navigation Center: ✓ Plotter: ✓ Autopilot: ✓ Radio: ✓ Compass: ✓ CD Player: ✓ VHF: ✓ Flat Screen TV: ✓ AIS: ✓

## INSPECTOR / HANDOVER SIGN-OFF

PREPARED BY

MotoComply ApS inspection team

FINAL HANDOVER CONFIRMATION

\_\_\_\_\_

MotoComply ApS inspection report for Vehicle ID 93298. This report is generated from the current listing record and should be updated if listing data or inspection notes change.