

Marine / Yacht Inspection Report

Report no.: MC-IR-31468 | Vehicle ID: 31468 | Issue date: 2026-06-10

| | | |
|--|-------------------------------------|--|
| LISTING 2016 Bavaria Vision 46 | TYPE Boat | STATUS available |
| BUILDER / MAKE Bavaria | MODEL Vision 46 | YEAR 2016 |
| CONDITION used | LOCATION European marina network | WARRANTY INFORMATION Inspection available before handover |

| | | |
|--|---------------------------------------|---|
| 100% Dealer reviewed inventory | Review Dealer certification | Prepared Handover preparation |
|--|---------------------------------------|---|

VESSEL IDENTITY AND TITLE REVIEW

| CHECKPOINT | FINDING / NOTE | RESULT |
|---|--------------------------------------|----------|
| Vehicle ID | 31468 | VERIFIED |
| Vessel type | Boat | VERIFIED |
| Builder / make | Bavaria | VERIFIED |
| Hull identification / registration number | To be confirmed at handover | PENDING |
| Original registration papers | Available for dealer handover review | VERIFIED |

HULL, DECK AND EXTERIOR SURVEY

| CHECKPOINT | FINDING / NOTE | RESULT |
|---------------------------|--|----------|
| Hull material | Not specified | PENDING |
| Hull visual inspection | Visible hull, gelcoat/paint and impact indicators reviewed | PASSED |
| Deck fittings and rails | Visible deck fittings, rails, cleats and access points checked | PASSED |
| Length / beam / draft | - / - / - | RECORDED |
| Current marina / location | European marina network | RECORDED |

ENGINE, PROPULSION AND SYSTEMS

| CHECKPOINT | FINDING / NOTE | RESULT |
|---------------------------|---|---------|
| Engine type | Not specified | PENDING |
| Engine power | Not specified | PENDING |
| Engine hours | Not specified | PENDING |
| Fuel type | Not specified | PENDING |
| Visible engine bay review | Leaks, corrosion indicators, belts, hoses and accessible systems reviewed | PASSED |

ACCOMMODATION AND ONBOARD EQUIPMENT

| CHECKPOINT | FINDING / NOTE | RESULT |
|--------------------|---|----------|
| Cabins | Not specified | PENDING |
| Berths | Not specified | PENDING |
| Water capacity | Not specified | PENDING |
| Fuel capacity | Not specified | PENDING |
| Included equipment | Year: 2016 Electrical Equipment Shore Power Inlet: ✓ Inverter: ✓ Electronics Depthsounder: ✓ Radar: ✓ Log-Speedometer: ✓ Radar Detector: ✓ Wind Speed and Direction: ✓ TV Set: ✓ Navigation Center: ✓ Plotter: ✓ DVD Player: ✓ Autopilot: ✓ Radio: ✓ Compass: ✓ CD Player: ✓ GPS: ✓ Cockpit Speakers: ✓ VHF: ✓ Flat Screen TV: ✓ AIS: ✓ Inside Equipment Bow Thruster: ✓ Electric Bilge Pump: ✓ Oven: ✓ Manual Bilge Pump: ✓ Microwave Oven: ✓ Marine Head: ✓ Air Conditioning: ✓ Electric Head: ✓ Heating: ✓ Hot Water: ✓ Refrigerator: ✓ Deep Freezer: ✓ Sea Water Pump: ✓ Battery Charger: ✓ Outside Equipment Teak Cockpit: ✓ | REVIEWED |

MARINE DELIVERY AND EXPORT READINESS

| CHECKPOINT | FINDING / NOTE | RESULT |
|-------------------------|--|-----------|
| Port delivery | Destination port delivery can be arranged where available | AVAILABLE |
| Export support | Export eligible listing | READY |
| Insurance handover note | Carrier/port handover should be documented before dispatch | REQUIRED |
| Survey note | Marine survey scope recorded for customer handover | ADVISORY |

LISTING EQUIPMENT AND NOTES

Year: 2016 Electrical Equipment Shore Power Inlet: ✓ Inverter: ✓ Electronics Depthsounder: ✓ Radar: ✓ Log-Speedometer: ✓ Radar Detector: ✓ Wind Speed and Direction: ✓ TV Set: ✓ Navigation Center: ✓ Plotter: ✓ DVD Player: ✓ Autopilot: ✓ Radio: ✓ Compass: ✓ CD Player: ✓ GPS: ✓ Cockpit Speakers: ✓ VHF: ✓ Flat Screen TV: ✓ AIS: ✓ Inside Equipment Bow Thruster: ✓ Electric Bilge Pump: ✓ Oven: ✓ Manual Bilge Pump: ✓ Microwave Oven: ✓ Marine Head: ✓ Air Conditioning: ✓ Electric Head: ✓ Heating: ✓ Hot Water: ✓ Refrigerator: ✓ Deep Freezer: ✓ Sea Water Pump: ✓ Battery Charger: ✓ Outside Equipment Teak Cockpit: ✓

INSPECTOR / HANDOVER SIGN-OFF

PREPARED BY

MotoComply ApS inspection team

FINAL HANDOVER CONFIRMATION

MotoComply ApS inspection report for Vehicle ID 31468. This report is generated from the current listing record and should be updated if listing data or inspection notes change.