PROFESSIONAL INSPECTION REPORT

Marine / Yacht Inspection Report

MotoComply ApS
CVR 46320565
0045 98 89 89 98
info@motocomplydk.com

Report no.: MC-IR-11169 | Vehicle ID: 11169 | Issue date: 2026-10-30

LISTING	TYPE	STATUS
2021 Regal 38 XO	Boat	Available
BUILDER / MAKE	**MODEL**	**YEAR**
Regal	38 XO	2021
CONDITION	**LOCATION**	**WARRANTY INFORMATION**
Used	European marina network	Inspection available before handover

100%	Review	Prepared
Dealer reviewed inventory	Dealer certification	Handover preparation

VESSEL IDENTITY AND TITLE REVIEW

CHECKPOINT	FINDING / NOTE	RESULT
Vehicle ID	11169	VERIFIED
Vessel type	Boat	VERIFIED
Builder / make	Regal	VERIFIED
Hull identification / registration number	To be confirmed at handover	PENDING
Original registration papers	Available for dealer handover review	VERIFIED

HULL, DECK AND EXTERIOR SURVEY

CHECKPOINT	FINDING / NOTE	RESULT
Hull material	Not specified	PENDING
Hull visual inspection	Visible hull, gelcoat/paint and impact indicators reviewed	PASSED
Deck fittings and rails	Visible deck fittings, rails, cleats and access points checked	PASSED
Length / beam / draft	- / - / -	RECORDED
Current marina / location	European marina network	RECORDED

ENGINE, PROPULSION AND SYSTEMS

CHECKPOINT	FINDING / NOTE	RESULT
Engine type	Not specified	PENDING
Engine power	Not specified	PENDING
Engine hours	Not specified	PENDING
Fuel type	Not specified	PENDING
Visible engine bay review	Leaks, corrosion indicators, belts, hoses and accessible systems reviewed	PASSED

ACCOMMODATION AND ONBOARD EQUIPMENT

CHECKPOINT	FINDING / NOTE	RESULT
Cabins	Not specified	PENDING
Berths	Not specified	PENDING
Water capacity	Not specified	PENDING
Fuel capacity	Not specified	PENDING
Included equipment	Year: 2021	REVIEWED

MARINE DELIVERY AND EXPORT READINESS

CHECKPOINT	FINDING / NOTE	RESULT
Port delivery	Destination port delivery can be arranged where available	AVAILABLE
Export support	Export eligible listing	READY
Insurance handover note	Carrier/port handover should be documented before dispatch	REQUIRED
Survey note	Marine survey scope recorded for customer handover	ADVISORY

LISTING EQUIPMENT AND NOTES

Year: 2021

INSPECTOR / HANDOVER SIGN-OFF

PREPARED BY	FINAL HANDOVER CONFIRMATION
MotoComply ApS inspection team	_____