PROFESSIONAL INSPECTION REPORT

Vehicle Inspection Report

MotoComply ApS
CVR 46320565
0045 98 89 89 98
info@motocomplydk.com

Report no.: MC-IR-92027 | Vehicle ID: 92027 | Issue date: 2026-10-31

LISTING	TYPE	STATUS
2017 Harley-Davidson XL 1200 X Forty Eight 48 ABS| Umbau| TOP Zustand!	Motorcycle	Available

MAKE	MODEL	YEAR
Harley-Davidson	XL 1200	2017

CONDITION	LOCATION	WARRANTY INFORMATION
Used	Denmark	Inspection available before handover

100%	Review	Prepared
Dealer reviewed inventory	Dealer certification	Handover preparation

IDENTITY AND DOCUMENTATION

CHECKPOINT	FINDING / NOTE	RESULT
Vehicle ID	92027	VERIFIED
Vehicle type	Motorcycle	VERIFIED
VIN / chassis number	To be confirmed at handover	PENDING
Registration date	2017-08-01	REVIEWED
Original registration papers	Available for dealer handover review	VERIFIED

MECHANICAL INSPECTION

CHECKPOINT	FINDING / NOTE	RESULT
Engine start and idle	Cold start, idle stability and visible leak check	PASSED
Engine size	1.202 cm³	VERIFIED
Transmission	inspection_report.value_transmission_Schaltgetriebe	VERIFIED
Powertrain response	Throttle response, clutch/drive engagement and abnormal noise check	PASSED
Cooling and fluids	Oil, coolant, brake fluid and visible hose condition checked	PASSED

SAFETY AND ROADWORTHINESS

CHECKPOINT	FINDING / NOTE	RESULT
Brakes	Front/rear braking response and visible disc/pad condition checked	PASSED
Tyres / wheels	Tyre condition, wheel alignment indicators and visible rim damage checked	PASSED
Suspension / steering	Steering movement, fork/shock condition and bearing play check	PASSED
Lights / horn / controls	Operational control check completed	PASSED
Mileage	2560	RECORDED

COSMETIC AND PREPARATION

CHECKPOINT	FINDING / NOTE	RESULT
Exterior color	Not specified	PENDING
Body panels / frame	Visible condition and preparation notes reviewed	PASSED
Dealer preparation	Prepared before customer handover	VERIFIED
Dealer certification	Dealer review required before final handover	PENDING

DELIVERY READINESS

CHECKPOINT	FINDING / NOTE	RESULT
Pickup readiness	Customer pickup can be scheduled after admin confirmation	READY
Road delivery	Covered or trailer delivery can be arranged where available	AVAILABLE
International delivery	International export support available	AVAILABLE
Handover documents	Contract, invoice and inspection report prepared for customer review	READY

LISTING EQUIPMENT AND NOTES

Make: Harley-Davidson Model: XL 1200 Version: X Forty Eight 48 ABS
Umbau
TOP Zustand! Body type: Motorbike Condition: Used First registration: 08/2017 Mileage: 2.560 km Engine: 1.202 cm³ Power: 49 kW (67 PS) Fuel: Benzin Transmission: Schaltgetriebe

INSPECTOR / HANDOVER SIGN-OFF

PREPARED BY	FINAL HANDOVER CONFIRMATION
MotoComply ApS inspection team	_____