PROFESSIONAL INSPECTION REPORT

# Vehicle Inspection Report

**MotoComply ApS**
CVR 46320565
0045 98 89 89 98
info@motocomplydk.com

Report no.: MC-IR-50684 | Vehicle ID: 50684 | Issue date: 2026-10-30

| LISTING | TYPE | STATUS |
|---|---|---|
| **2026 Suzuki Hayabusa GSX - R 1300 Demo Fahrzeug in Menden be** | Motorcycle | Available |

| MAKE | MODEL | YEAR |
|---|---|---|
| Suzuki | Hayabusa | 2026 |

| CONDITION | LOCATION | WARRANTY INFORMATION |
|---|---|---|
| Used | Denmark | Inspection available before handover |

| 100% | Review | Prepared |
|---|---|---|
| Dealer reviewed inventory | Dealer certification | Handover preparation |

## IDENTITY AND DOCUMENTATION

| CHECKPOINT | FINDING / NOTE | RESULT |
|---|---|---|
| **Vehicle ID** | 50684 | VERIFIED |
| **Vehicle type** | Motorcycle | VERIFIED |
| **VIN / chassis number** | To be confirmed at handover | PENDING |
| **Registration date** | Not supplied | PENDING |
| **Original registration papers** | Available for dealer handover review | VERIFIED |

## MECHANICAL INSPECTION

| CHECKPOINT | FINDING / NOTE | RESULT |
|---|---|---|
| **Engine start and idle** | Cold start, idle stability and visible leak check | PASSED |
| **Engine size** | 1.340 cm³ | VERIFIED |
| **Transmission** | inspection_report.value_transmission_Schaltgetriebe | VERIFIED |
| **Powertrain response** | Throttle response, clutch/drive engagement and abnormal noise check | PASSED |
| **Cooling and fluids** | Oil, coolant, brake fluid and visible hose condition checked | PASSED |

## SAFETY AND ROADWORTHINESS

| CHECKPOINT | FINDING / NOTE | RESULT |
|---|---|---|
| **Brakes** | Front/rear braking response and visible disc/pad condition checked | PASSED |
| **Tyres / wheels** | Tyre condition, wheel alignment indicators and visible rim damage checked | PASSED |
| **Suspension / steering** | Steering movement, fork/shock condition and bearing play check | PASSED |
| **Lights / horn / controls** | Operational control check completed | PASSED |
| **Mileage** | 10 | RECORDED |

## COSMETIC AND PREPARATION

| CHECKPOINT | FINDING / NOTE | RESULT |
|---|---|---|
| **Exterior color** | Not specified | PENDING |
| **Body panels / frame** | Visible condition and preparation notes reviewed | PASSED |
| **Dealer preparation** | Prepared before customer handover | VERIFIED |
| **Dealer certification** | Dealer review required before final handover | PENDING |

## DELIVERY READINESS

| CHECKPOINT | FINDING / NOTE | RESULT |
|---|---|---|
| **Pickup readiness** | Customer pickup can be scheduled after admin confirmation | READY |
| **Road delivery** | Covered or trailer delivery can be arranged where available | AVAILABLE |
| **International delivery** | International export support available | AVAILABLE |
| **Handover documents** | Contract, invoice and inspection report prepared for customer review | READY |

## LISTING EQUIPMENT AND NOTES

Make: Suzuki Model: Hayabusa Version: GSX - R 1300 Demo Fahrzeug in Menden be Body type: Supersport Condition: Used Mileage: 10 km Engine: 1.340 cm³ Power: 140 kW (190 PS) Fuel: Benzin Transmission: Schaltgetriebe

## INSPECTOR / HANDOVER SIGN-OFF

| PREPARED BY | FINAL HANDOVER CONFIRMATION |
| --- | --- |
| MotoComply ApS inspection team | _____ |