INFORME DE INSPECCIÓN PROFESIONAL

Informe de inspección barco / yate

MotoComply ApS
CVR 46320565
0045 98 89 89 98
info@motocomplydk.com

Informe n.º: MC-IR-91147 | ID del vehículo: 91147 | Fecha de emisión: 2026-10-30

ANUNCIO	TIPO	ESTADO
2024 Hanse 360	Barco	Disponible
CONSTRUCTOR / MARCA	**MODELO**	**AÑO**
Hanse	360	2024
ESTADO	**UBICACIÓN**	**INFORMACIÓN DE GARANTÍA**
Usado	European marina network	Inspection available before handover

100%	Review	Prepared
Dealer reviewed inventory	Dealer certification	Handover preparation

VESSEL IDENTITY AND TITLE REVIEW

PUNTO DE CONTROL	RESULTADO / NOTA	RESULTADO
ID del vehículo	91147	VERIFICADO
Vessel type	Barco	VERIFICADO
Constructor / marca	Hanse	VERIFICADO
Hull identification / registration number	A confirmar en la entrega	PENDIENTE
Original registration papers	Available for dealer handover review	VERIFICADO

HULL, DECK AND EXTERIOR SURVEY

PUNTO DE CONTROL	RESULTADO / NOTA	RESULTADO
Hull material	No especificado	PENDIENTE
Hull visual inspection	Visible hull, gelcoat/paint and impact indicators reviewed	APROBADO
Deck fittings and rails	Visible deck fittings, rails, cleats and access points checked	APROBADO
Length / beam / draft	- / - / -	REGISTRADO
Current marina / location	European marina network	REGISTRADO

ENGINE, PROPULSION AND SYSTEMS

PUNTO DE CONTROL	RESULTADO / NOTA	RESULTADO
Engine type	No especificado	PENDIENTE
Engine power	No especificado	PENDIENTE
Engine hours	No especificado	PENDIENTE
Fuel type	No especificado	PENDIENTE
Visible engine bay review	Leaks, corrosion indicators, belts, hoses and accessible systems reviewed	APROBADO

ACCOMMODATION AND ONBOARD EQUIPMENT

PUNTO DE CONTROL	RESULTADO / NOTA	RESULTADO
Cabins	No especificado	PENDIENTE
Berths	No especificado	PENDIENTE
Water capacity	No especificado	PENDIENTE
Fuel capacity	No especificado	PENDIENTE
Included equipment	Year: 2024 Electrical Equipment Shore Power Inlet: ✓ Electronics Depthsounder: ✓ Log-Speedometer: ✓ Wind Speed and Direction: ✓ Plotter: ✓ Autopilot: ✓ Radio: ✓ Compass: ✓ GPS: ✓ Cockpit Speakers: ✓ VHF: ✓ Inside Equipment Bow Thruster: ✓ Electric Bilge Pump: ✓ Oven: ✓ Manual Bilge Pump: ✓ Marine Head: ✓ Hot Water: ✓ Refrigerator: ✓ Battery Charger: ✓ Outside Equipment Teak Cockpit: ✓ Cockpit Shower: ✓ Electric Winch: ✓ Cockpit Cushions: ✓ Cockpit Table: ✓ Swimming Ladder: ✓ Rigging Steering Wheel: ✓ Sails Fully Battened Mainsail: ✓ Genoa: ✓	REVISADO

MARINE DELIVERY AND EXPORT READINESS

PUNTO DE CONTROL	RESULTADO / NOTA	RESULTADO
Port delivery	Destination port delivery can be arranged where available	DISPONIBLE
Export support	Export eligible listing	LISTO
Insurance handover note	Carrier/port handover should be documented before dispatch	REQUERIDO
Survey note	Marine survey scope recorded for customer handover	AVISO

LISTING EQUIPMENT AND NOTES

Year: 2024 Electrical Equipment Shore Power Inlet: ✓ Electronics Depthsounder: ✓ Log-Speedometer: ✓ Wind Speed and Direction: ✓ Plotter: ✓ Autopilot: ✓ Radio: ✓ Compass: ✓ GPS: ✓ Cockpit Speakers: ✓ VHF: ✓ Inside Equipment Bow Thruster: ✓ Electric Bilge Pump: ✓ Oven: ✓ Manual Bilge Pump: ✓ Marine Head: ✓ Hot Water: ✓ Refrigerator: ✓ Battery Charger: ✓ Outside Equipment Teak Cockpit: ✓ Cockpit Shower: ✓ Electric Winch: ✓ Cockpit Cushions: ✓ Cockpit Table: ✓ Swimming Ladder: ✓ Rigging Steering Wheel: ✓ Sails Fully Battened Mainsail: ✓ Genoa: ✓

INSPECTOR / HANDOVER SIGN-OFF

PREPARED BY	FINAL HANDOVER CONFIRMATION
MotoComply ApS inspection team	_____