

Marine / Yacht Inspection Report

Report no.: MC-IR-92065 | Vehicle ID: 92065 | Fecha de emisión: 2026-06-10

| | | |
|--|-------------------------------------|--|
| LISTING 2026 Mega Yacht Custom | TIPO Yacht | ESTADO available |
| BUILDER / MAKE Mega | MODEL Yacht Custom | AÑO 2026 |
| ESTADO used | LOCATION European marina network | WARRANTY INFORMATION Inspection available before handover |

| | | |
|--|---------------------------------------|---|
| 100% Dealer reviewed inventory | Review Dealer certification | Prepared Handover preparation |
|--|---------------------------------------|---|

VESSEL IDENTITY AND TITLE REVIEW

| CHECKPOINT | FINDING / NOTE | RESULT |
|---|--------------------------------------|----------|
| Vehicle ID | 92065 | VERIFIED |
| Vessel type | Yacht | VERIFIED |
| Builder / make | Mega | VERIFIED |
| Hull identification / registration number | To be confirmed at handover | PENDING |
| Original registration papers | Available for dealer handover review | VERIFIED |

HULL, DECK AND EXTERIOR SURVEY

| CHECKPOINT | FINDING / NOTE | RESULT |
|---------------------------|--|----------|
| Hull material | Not specified | PENDING |
| Hull visual inspection | Visible hull, gelcoat/paint and impact indicators reviewed | PASSED |
| Deck fittings and rails | Visible deck fittings, rails, cleats and access points checked | PASSED |
| Length / beam / draft | - / - / - | RECORDED |
| Current marina / location | European marina network | RECORDED |

ENGINE, PROPULSION AND SYSTEMS

| CHECKPOINT | FINDING / NOTE | RESULT |
|---------------------------|---|---------|
| Engine type | Not specified | PENDING |
| Engine power | Not specified | PENDING |
| Engine hours | Not specified | PENDING |
| Fuel type | Not specified | PENDING |
| Visible engine bay review | Leaks, corrosion indicators, belts, hoses and accessible systems reviewed | PASSED |

ACCOMMODATION AND ONBOARD EQUIPMENT

| CHECKPOINT | FINDING / NOTE | RESULT |
|--------------------|--|----------|
| Cabins | Not specified | PENDING |
| Berths | Not specified | PENDING |
| Water capacity | Not specified | PENDING |
| Fuel capacity | Not specified | PENDING |
| Included equipment | Year: 2026 Electrical Equipment Shore Power Inlet: ✓ Generator: ✓ Inverter: ✓ Electronics Depthsounder: ✓ Radar: ✓ Log-Speedometer: ✓ Wind Speed and Direction: ✓ Computer: ✓ Repeater(s): ✓ TV Set: ✓ Navigation Center: ✓ Plotter: ✓ Autopilot: ✓ Radio: ✓ Compass: ✓ GPS: ✓ Cockpit Speakers: ✓ VHF: ✓ Inside Equipment Stern Thruster: ✓ Dishwasher: ✓ Bow Thruster: ✓ Washing Machine: ✓ Electric Bilge Pump: ✓ Oven: ✓ Manual Bilge Pump: ✓ Microwave Oven: ✓ Air Compressor: ✓ Air Conditioning: ✓ Electric Head: ✓ Heating: ✓ Hot Water: ✓ Refrigerator: ✓ Fresh Water Maker: ✓ Deep Freezer: ✓ Sea Water Pump: ✓ Battery Charger: ✓ | REVIEWED |

MARINE DELIVERY AND EXPORT READINESS

| CHECKPOINT | FINDING / NOTE | RESULT |
|-------------------------|--|-----------|
| Port delivery | Destination port delivery can be arranged where available | AVAILABLE |
| Export support | Export eligible listing | READY |
| Insurance handover note | Carrier/port handover should be documented before dispatch | REQUIRED |
| Survey note | Marine survey scope recorded for customer handover | ADVISORY |

LISTING EQUIPMENT AND NOTES

Year: 2026 Electrical Equipment Shore Power Inlet: ✓ Generator: ✓ Inverter: ✓ Electronics Depthsounder: ✓ Radar: ✓ Log-Speedometer: ✓ Wind Speed and Direction: ✓ Computer: ✓ Repeater(s): ✓ TV Set: ✓ Navigation Center: ✓ Plotter: ✓ Autopilot: ✓ Radio: ✓ Compass: ✓ GPS: ✓ Cockpit Speakers: ✓ VHF: ✓ Inside Equipment Stern Thruster: ✓ Dishwasher: ✓ Bow Thruster: ✓ Washing Machine: ✓ Electric Bilge Pump: ✓ Oven: ✓ Manual Bilge Pump: ✓ Microwave Oven: ✓ Air Compressor: ✓ Air Conditioning: ✓ Electric Head: ✓ Heating: ✓ Hot Water: ✓ Refrigerator: ✓ Fresh Water Maker: ✓ Deep Freezer: ✓ Sea Water Pump: ✓ Battery Charger: ✓

INSPECTOR / HANDOVER SIGN-OFF

PREPARED BY

MotoComply ApS inspection team

FINAL HANDOVER CONFIRMATION

MotoComply ApS inspection report for Vehicle ID 92065. This report is generated from the current listing record and should be updated if listing data or inspection notes change.