INFORME DE INSPECCIÓN PROFESIONAL

Informe de inspección del vehículo

MotoComply ApS
CVR 46320565
0045 98 89 89 98
info@motocomplydk.com

Informe n.º: MC-IR-29406 | ID del vehículo: 29406 | Fecha de emisión: 2026-10-31

ANUNCIO	TIPO	ESTADO
2019 MV AGUSTA Dragster Dragster 800 RR ABS Custom	Motocicleta	Disponible
MARCA	**MODELO**	**AÑO**
MV AGUSTA	Dragster	2019
ESTADO	**UBICACIÓN**	**INFORMACIÓN DE GARANTÍA**
Usado	Denmark	Inspection available before handover

100%	Review	Prepared
Dealer reviewed inventory	Dealer certification	Handover preparation

IDENTIDAD Y DOCUMENTACIÓN

PUNTO DE CONTROL	RESULTADO / NOTA	RESULTADO
ID del vehículo	29406	VERIFICADO
Tipo de vehículo	Motocicleta	VERIFICADO
VIN / número de chasis	A confirmar en la entrega	PENDIENTE
Fecha de matriculación	2019-02-01	REVISADO
Original registration papers	Available for dealer handover review	VERIFICADO

INSPECCIÓN MECÁNICA

PUNTO DE CONTROL	RESULTADO / NOTA	RESULTADO
Engine start and idle	Cold start, idle stability and visible leak check	APROBADO
Engine size	798	VERIFICADO
Transmission	Manual	VERIFICADO
Powertrain response	Throttle response, clutch/drive engagement and abnormal noise check	APROBADO
Cooling and fluids	Oil, coolant, brake fluid and visible hose condition checked	APROBADO

SEGURIDAD Y APTITUD VIAL

PUNTO DE CONTROL	RESULTADO / NOTA	RESULTADO
Brakes	Front/rear braking response and visible disc/pad condition checked	APROBADO
Tyres / wheels	Tyre condition, wheel alignment indicators and visible rim damage checked	APROBADO
Suspension / steering	Steering movement, fork/shock condition and bearing play check	APROBADO
Lights / horn / controls	Operational control check completed	APROBADO
Mileage	1747	REGISTRADO

ASPECTO Y PREPARACIÓN

PUNTO DE CONTROL	RESULTADO / NOTA	RESULTADO
Exterior color	black	REGISTRADO
Body panels / frame	Visible condition and preparation notes reviewed	APROBADO
Dealer preparation	Prepared before customer handover	VERIFICADO
Dealer certification	Dealer review required before final handover	PENDIENTE

PREPARACIÓN PARA ENTREGA

PUNTO DE CONTROL	RESULTADO / NOTA	RESULTADO
Pickup readiness	Customer pickup can be scheduled after admin confirmation	LISTO
Road delivery	Covered or trailer delivery can be arranged where available	DISPONIBLE
International delivery	International export support available	DISPONIBLE
Handover documents	Contract, invoice and inspection report prepared for customer review	LISTO

LISTING EQUIPMENT AND NOTES

Make: MV AGUSTA Model: Dragster Version: Dragster 800 RR ABS Custom Body type: street-bike Condition: Used Year: 2019 First registration: 2019-02-01 Mileage: 1747 Engine: 798 Power: 140 Fuel: petrol Transmission: manual Color: black Accident history: False

INSPECTOR / HANDOVER SIGN-OFF

PREPARED BY	FINAL HANDOVER CONFIRMATION
MotoComply ApS inspection team	_____