INFORME DE INSPECCIÓN PROFESIONAL

Informe de inspección del vehículo

MotoComply ApS
CVR 46320565
0045 98 89 89 98
info@motocomplydk.com

Informe n.º: MC-IR-50684 | ID del vehículo: 50684 | Fecha de emisión: 2026-10-31

ANUNCIO	TIPO	ESTADO
2026 Suzuki Hayabusa GSX - R 1300 Demo Fahrzeug in Menden be	Motocicleta	Disponible

MARCA	MODELO	AÑO
Suzuki	Hayabusa	2026

ESTADO	UBICACIÓN	INFORMACIÓN DE GARANTÍA
Usado	Denmark	Inspection available before handover

100%	Review	Prepared
Dealer reviewed inventory	Dealer certification	Handover preparation

IDENTIDAD Y DOCUMENTACIÓN

PUNTO DE CONTROL	RESULTADO / NOTA	RESULTADO
ID del vehículo	50684	VERIFICADO
Tipo de vehículo	Motocicleta	VERIFICADO
VIN / número de chasis	A confirmar en la entrega	PENDIENTE
Fecha de matriculación	No suministrado	PENDIENTE
Original registration papers	Available for dealer handover review	VERIFICADO

INSPECCIÓN MECÁNICA

PUNTO DE CONTROL	RESULTADO / NOTA	RESULTADO
Engine start and idle	Cold start, idle stability and visible leak check	APROBADO
Engine size	1.340 cm³	VERIFICADO
Transmission	inspection_report.value_transmission_Schaltgetriebe	VERIFICADO
Powertrain response	Throttle response, clutch/drive engagement and abnormal noise check	APROBADO
Cooling and fluids	Oil, coolant, brake fluid and visible hose condition checked	APROBADO

SEGURIDAD Y APTITUD VIAL

PUNTO DE CONTROL	RESULTADO / NOTA	RESULTADO
Brakes	Front/rear braking response and visible disc/pad condition checked	APROBADO
Tyres / wheels	Tyre condition, wheel alignment indicators and visible rim damage checked	APROBADO
Suspension / steering	Steering movement, fork/shock condition and bearing play check	APROBADO
Lights / horn / controls	Operational control check completed	APROBADO
Mileage	10	REGISTRADO

ASPECTO Y PREPARACIÓN

PUNTO DE CONTROL	RESULTADO / NOTA	RESULTADO
Exterior color	No especificado	PENDIENTE
Body panels / frame	Visible condition and preparation notes reviewed	APROBADO
Dealer preparation	Prepared before customer handover	VERIFICADO
Dealer certification	Dealer review required before final handover	PENDIENTE

PREPARACIÓN PARA ENTREGA

PUNTO DE CONTROL	RESULTADO / NOTA	RESULTADO
Pickup readiness	Customer pickup can be scheduled after admin confirmation	LISTO
Road delivery	Covered or trailer delivery can be arranged where available	DISPONIBLE
International delivery	International export support available	DISPONIBLE
Handover documents	Contract, invoice and inspection report prepared for customer review	LISTO

LISTING EQUIPMENT AND NOTES

Make: Suzuki Model: Hayabusa Version: GSX - R 1300 Demo Fahrzeug in Menden be Body type: Supersport Condition: Used Mileage: 10 km Engine: 1.340 cm³ Power: 140 kW (190 PS) Fuel: Benzin Transmission: Schaltgetriebe

INSPECTOR / HANDOVER SIGN-OFF

PREPARED BY	FINAL HANDOVER CONFIRMATION
MotoComply ApS inspection team	_____