

# Vehicle Inspection Report

Report no.: MC-IR-72773 | Vehicle ID: 72773 | Fecha de emisión: 2026-06-10

|  |                     |  |
|--|---------------------|--|
| LISTING<br><b>2017 CAN-AM Spyder Spyder F3-S Daytona SE6</b> | TIPO<br>Trike       | ESTADO<br>available  |
| MAKE<br>CAN-AM   | MODEL<br>Spyder     | AÑO<br>2017  |
| ESTADO<br>used   | LOCATION<br>Denmark | WARRANTY INFORMATION<br>Inspection available before handover |

|  |                                       |   |
|--|---------------------------------------|---|
| <b>100%</b><br>Dealer reviewed inventory | <b>Review</b><br>Dealer certification | <b>Prepared</b><br>Handover preparation |
|--|---------------------------------------|---|

## IDENTITY AND DOCUMENTATION

| CHECKPOINT                   | FINDING / NOTE                       | RESULT   |
|------------------------------|--------------------------------------|----------|
| Vehicle ID                   | 72773                                | VERIFIED |
| Vehicle type                 | Trike                                | VERIFIED |
| VIN / chassis number         | To be confirmed at handover          | PENDING  |
| Registration date            | 2017-03-01                           | REVIEWED |
| Original registration papers | Available for dealer handover review | VERIFIED |

## MECHANICAL INSPECTION

| CHECKPOINT            | FINDING / NOTE  | RESULT   |
|-----------------------|---|----------|
| Engine start and idle | Cold start, idle stability and visible leak check                   | PASSED   |
| Engine size           | 1330  | VERIFIED |
| Transmission          | semi-automatic  | VERIFIED |
| Powertrain response   | Throttle response, clutch/drive engagement and abnormal noise check | PASSED   |
| Cooling and fluids    | Oil, coolant, brake fluid and visible hose condition checked        | PASSED   |

## SAFETY AND ROADWORTHINESS

| CHECKPOINT               | FINDING / NOTE  | RESULT   |
|--------------------------|---|----------|
| Brakes                   | Front/rear braking response and visible disc/pad condition checked        | PASSED   |
| Tyres / wheels           | Tyre condition, wheel alignment indicators and visible rim damage checked | PASSED   |
| Suspension / steering    | Steering movement, fork/shock condition and bearing play check            | PASSED   |
| Lights / horn / controls | Operational control check completed                                       | PASSED   |
| Mileage                  | 12000   | RECORDED |

## COSMETIC AND PREPARATION

| CHECKPOINT           | FINDING / NOTE                                   | RESULT   |
|----------------------|--|----------|
| Exterior color       | yellow   | RECORDED |
| Body panels / frame  | Visible condition and preparation notes reviewed | PASSED   |
| Dealer preparation   | Prepared before customer handover                | VERIFIED |
| Dealer certification | Dealer review required before final handover     | PENDING  |

## DELIVERY READINESS

| CHECKPOINT             | FINDING / NOTE   | RESULT    |
|------------------------|--|-----------|
| Pickup readiness       | Customer pickup can be scheduled after admin confirmation            | READY     |
| Road delivery          | Covered or trailer delivery can be arranged where available          | AVAILABLE |
| International delivery | International export support available                               | AVAILABLE |
| Handover documents     | Contract, invoice and inspection report prepared for customer review | READY     |

## LISTING EQUIPMENT AND NOTES

Make: CAN-AM Model: Spyder Version: Spyder F3-S Daytona SE6 Body type: trike Condition: Used Year: 2017 First registration: 2017-03-01 Mileage: 12000 Engine: 1330 Power: 112 Fuel: petrol Transmission: semi-automatic Color: yellow Accident history: False

## INSPECTOR / HANDOVER SIGN-OFF

|   |                                      |
|---|--------------------------------------|
| PREPARED BY<br>MotoComply ApS inspection team | FINAL HANDOVER CONFIRMATION<br>_____ |
|---|--------------------------------------|

---

MotoComply ApS inspection report for Vehicle ID 72773. This report is generated from the current listing record and should be updated if listing data or inspection notes change.