RAPPORT D’INSPECTION PROFESSIONNEL

Rapport d’inspection bateau / yacht

MotoComply ApS
CVR 46320565
0045 98 89 89 98
info@motocomplydk.com

Rapport n°: MC-IR-49806 | ID véhicule: 49806 | Date d’émission: 2026-10-31

ANNONCE	TYPE	STATUT
2013 Gemini Legacy	Bateau	Disponible
CONSTRUCTEUR / MARQUE	MODÈLE	ANNÉE
Gemini	Legacy	2013
ÉTAT	LOCALISATION	INFORMATIONS DE GARANTIE
Occasion	European marina network	Inspection available before handover

100%	Examen	Préparé
Stock vérifié par le concessionnaire	Certification concessionnaire	Préparation de remise

VESSEL IDENTITY AND TITLE REVIEW

POINT DE CONTRÔLE	CONSTAT / NOTE	RÉSULTAT
ID véhicule	49806	VÉRIFIÉ
Vessel type	Bateau	VÉRIFIÉ
Constructeur / marque	Gemini	VÉRIFIÉ
Hull identification / registration number	À confirmer lors de la remise	EN ATTENTE
Documents d’immatriculation originaux	Available for dealer handover review	VÉRIFIÉ

HULL, DECK AND EXTERIOR SURVEY

POINT DE CONTRÔLE	CONSTAT / NOTE	RÉSULTAT
Hull material	Non spécifié	EN ATTENTE
Hull visual inspection	Visible hull, gelcoat/paint and impact indicators reviewed	RÉUSSI
Deck fittings and rails	Visible deck fittings, rails, cleats and access points checked	RÉUSSI
Length / beam / draft	- / - / -	ENREGISTRÉ
Current marina / location	European marina network	ENREGISTRÉ

ENGINE, PROPULSION AND SYSTEMS

POINT DE CONTRÔLE	CONSTAT / NOTE	RÉSULTAT
Engine type	Non spécifié	EN ATTENTE
Engine power	Non spécifié	EN ATTENTE
Engine hours	Non spécifié	EN ATTENTE
Fuel type	Non spécifié	EN ATTENTE
Visible engine bay review	Leaks, corrosion indicators, belts, hoses and accessible systems reviewed	RÉUSSI

ACCOMMODATION AND ONBOARD EQUIPMENT

POINT DE CONTRÔLE	CONSTAT / NOTE	RÉSULTAT
Cabins	Non spécifié	EN ATTENTE
Berths	Non spécifié	EN ATTENTE
Water capacity	Non spécifié	EN ATTENTE
Fuel capacity	Non spécifié	EN ATTENTE
Included equipment	Year: 2013 Electrical Equipment Shore Power Inlet: ✓ Generator: Portable Yamaha 2300/1800 Electronics Depthsounder: ✓ Wind Speed and Direction: RAYMARINE Navigation Center: ✓ Plotter: Garmin 740S NEW Autopilot: Raymarine wheel pilot Need repair Radio: ✓ Compass: ✓ GPS: Garmin 740S NEW Cockpit Speakers: ✓ VHF: ✓ Inside Equipment Electric Bilge Pump: ✓ Oven: ✓ Manual Bilge Pump: ✓ Microwave Oven: ✓ Air Conditioning: ✓ Electric Head: ✓ Refrigerator: ✓ Battery Charger: ✓ Outside Equipment Cockpit Shower: ✓ Davit(s): ✓ Tender: Additional Cockpit Cushions: ✓ Cockpit Table: ✓ Swimming Ladder: ✓ Rigging Steering Wheel: ✓ Sails Fully Battened Mainsail: ✓ Furling Genoa: ✓	EXAMINÉ

MARINE DELIVERY AND EXPORT READINESS

POINT DE CONTRÔLE	CONSTAT / NOTE	RÉSULTAT
Port delivery	Destination port delivery can be arranged where available	DISPONIBLE
Export support	Export eligible listing	PRÊT
Insurance handover note	Carrier/port handover should be documented before dispatch	REQUIS
Survey note	Marine survey scope recorded for customer handover	CONSEIL

ÉQUIPEMENT ET NOTES DE L’ANNONCE

Year: 2013 Electrical Equipment Shore Power Inlet: ✓ Generator: Portable Yamaha 2300/1800 Electronics Depthsounder: ✓ Wind Speed and Direction: RAYMARINE Navigation Center: ✓ Plotter: Garmin 740S NEW Autopilot: Raymarine wheel pilot Need repair Radio: ✓ Compass: ✓ GPS: Garmin 740S NEW Cockpit Speakers: ✓ VHF: ✓ Inside Equipment Electric Bilge Pump: ✓ Oven: ✓ Manual Bilge Pump: ✓ Microwave Oven: ✓ Air Conditioning: ✓ Electric Head: ✓ Refrigerator: ✓ Battery Charger: ✓ Outside Equipment Cockpit Shower: ✓ Davit(s): ✓ Tender: Additional Cockpit Cushions: ✓ Cockpit Table: ✓ Swimming Ladder: ✓ Rigging Steering Wheel: ✓ Sails Fully Battened Mainsail: ✓ Furling Genoa: ✓

VALIDATION INSPECTION / REMISE

PRÉPARÉ PAR	CONFIRMATION FINALE DE REMISE
Équipe d’inspection MotoComply ApS	_____