

# Vehicle Inspection Report

Report no.: MC-IR-29406 | Vehicle ID: 29406 | Date d'émission: 2026-06-13

LISTING <b>2019 MV AGUSTA Dragster Dragster 800 RR ABS Custom</b>	TYPE Motorcycle	STATUT available
MAKE MV AGUSTA	MODEL Dragster	ANNÉE 2019
ÉTAT used	LOCATION Denmark	WARRANTY INFORMATION Inspection available before handover

<b>100%</b> Dealer reviewed inventory	<b>Review</b> Dealer certification	<b>Prepared</b> Handover preparation
--	---------------------------------------	---

## IDENTITY AND DOCUMENTATION

CHECKPOINT	FINDING / NOTE	RESULT
Vehicle ID	29406	VERIFIED
Vehicle type	Motorcycle	VERIFIED
VIN / chassis number	To be confirmed at handover	PENDING
Registration date	2019-02-01	REVIEWED
Original registration papers	Available for dealer handover review	VERIFIED

## MECHANICAL INSPECTION

CHECKPOINT	FINDING / NOTE	RESULT
Engine start and idle	Cold start, idle stability and visible leak check	PASSED
Engine size	798	VERIFIED
Transmission	manual	VERIFIED
Powertrain response	Throttle response, clutch/drive engagement and abnormal noise check	PASSED
Cooling and fluids	Oil, coolant, brake fluid and visible hose condition checked	PASSED

## SAFETY AND ROADWORTHINESS

CHECKPOINT	FINDING / NOTE	RESULT
<b>Brakes</b>	Front/rear braking response and visible disc/pad condition checked	<b>PASSED</b>
<b>Tyres / wheels</b>	Tyre condition, wheel alignment indicators and visible rim damage checked	<b>PASSED</b>
<b>Suspension / steering</b>	Steering movement, fork/shock condition and bearing play check	<b>PASSED</b>
<b>Lights / horn / controls</b>	Operational control check completed	<b>PASSED</b>
<b>Mileage</b>	1747	<b>RECORDED</b>

## COSMETIC AND PREPARATION

CHECKPOINT	FINDING / NOTE	RESULT
<b>Exterior color</b>	black	<b>RECORDED</b>
<b>Body panels / frame</b>	Visible condition and preparation notes reviewed	<b>PASSED</b>
<b>Dealer preparation</b>	Prepared before customer handover	<b>VERIFIED</b>
<b>Dealer certification</b>	Dealer review required before final handover	<b>PENDING</b>

## DELIVERY READINESS

CHECKPOINT	FINDING / NOTE	RESULT
<b>Pickup readiness</b>	Customer pickup can be scheduled after admin confirmation	<b>READY</b>
<b>Road delivery</b>	Covered or trailer delivery can be arranged where available	<b>AVAILABLE</b>
<b>International delivery</b>	International export support available	<b>AVAILABLE</b>
<b>Handover documents</b>	Contract, invoice and inspection report prepared for customer review	<b>READY</b>

## LISTING EQUIPMENT AND NOTES

Make: MV AGUSTA Model: Dragster Version: Dragster 800 RR ABS Custom Body type: street-bike Condition: Used Year: 2019 First registration: 2019-02-01 Mileage: 1747 Engine: 798 Power: 140 Fuel: petrol Transmission: manual Color: black Accident history: False

## INSPECTOR / HANDOVER SIGN-OFF

PREPARED BY MotoComply ApS inspection team	FINAL HANDOVER CONFIRMATION _____
---	--------------------------------------

---

MotoComply ApS inspection report for Vehicle ID 29406. This report is generated from the current listing record and should be updated if listing data or inspection notes change.