

Vehicle Inspection Report

Report no.: MC-IR-32685 | Vehicle ID: 32685 | Kiállítás dátuma: 2026-06-10

| | | |
|--|---------------------|--|
| LISTING 2019 CAN-AM Spyder Spyder F3-S SE6 | TÍPUS Trike | ÁLLAPOT available |
| MAKE CAN-AM | MODEL Spyder | ÉVJÁRAT 2019 |
| ÁLLAPOT used | LOCATION Denmark | WARRANTY INFORMATION Inspection available before handover |

| | | |
|--|---------------------------------------|---|
| 100% Dealer reviewed inventory | Review Dealer certification | Prepared Handover preparation |
|--|---------------------------------------|---|

IDENTITY AND DOCUMENTATION

| CHECKPOINT | FINDING / NOTE | RESULT |
|------------------------------|--------------------------------------|----------|
| Vehicle ID | 32685 | VERIFIED |
| Vehicle type | Trike | VERIFIED |
| VIN / chassis number | To be confirmed at handover | PENDING |
| Registration date | 2019-05-01 | REVIEWED |
| Original registration papers | Available for dealer handover review | VERIFIED |

MECHANICAL INSPECTION

| CHECKPOINT | FINDING / NOTE | RESULT |
|-----------------------|---|----------|
| Engine start and idle | Cold start, idle stability and visible leak check | PASSED |
| Engine size | 1330 | VERIFIED |
| Transmission | semi-automatic | VERIFIED |
| Powertrain response | Throttle response, clutch/drive engagement and abnormal noise check | PASSED |
| Cooling and fluids | Oil, coolant, brake fluid and visible hose condition checked | PASSED |

SAFETY AND ROADWORTHINESS

| CHECKPOINT | FINDING / NOTE | RESULT |
|--------------------------|---|----------|
| Brakes | Front/rear braking response and visible disc/pad condition checked | PASSED |
| Tyres / wheels | Tyre condition, wheel alignment indicators and visible rim damage checked | PASSED |
| Suspension / steering | Steering movement, fork/shock condition and bearing play check | PASSED |
| Lights / horn / controls | Operational control check completed | PASSED |
| Mileage | 13000 | RECORDED |

COSMETIC AND PREPARATION

| CHECKPOINT | FINDING / NOTE | RESULT |
|----------------------|--|----------|
| Exterior color | blue | RECORDED |
| Body panels / frame | Visible condition and preparation notes reviewed | PASSED |
| Dealer preparation | Prepared before customer handover | VERIFIED |
| Dealer certification | Dealer review required before final handover | PENDING |

DELIVERY READINESS

| CHECKPOINT | FINDING / NOTE | RESULT |
|------------------------|--|-----------|
| Pickup readiness | Customer pickup can be scheduled after admin confirmation | READY |
| Road delivery | Covered or trailer delivery can be arranged where available | AVAILABLE |
| International delivery | International export support available | AVAILABLE |
| Handover documents | Contract, invoice and inspection report prepared for customer review | READY |

LISTING EQUIPMENT AND NOTES

Make: CAN-AM Model: Spyder Version: Spyder F3-S SE6 Body type: trike Condition: Used Year: 2019 First registration: 2019-05-01
Mileage: 13000 Engine: 1330 Power: 115 Fuel: petrol Transmission: semi-automatic Color: blue Accident history: False

INSPECTOR / HANDOVER SIGN-OFF

| | |
|---|--------------------------------------|
| PREPARED BY MotoComply ApS inspection team | FINAL HANDOVER CONFIRMATION _____ |
|---|--------------------------------------|