RAPPORTO DI ISPEZIONE PROFESSIONALE

Rapporto ispezione barca / yacht

MotoComply ApS
CVR 46320565
0045 98 89 89 98
info@motocomplydk.com

Rapporto n.: MC-IR-53790 | ID veicolo: 53790 | Data di emissione: 2026-10-31

ANNUNCIO	TIPO	STATO
2023 Delta Powerboats 33 Coupe	Barca	Disponibile
COSTRUTTORE / MARCA	**MODELLO**	**ANNO**
Delta	Powerboats 33 Coupe	2023
CONDIZIONE	**LOCALITÀ**	**INFORMAZIONI GARANZIA**
Usato	European marina network	Inspection available before handover

100%	Review	Prepared
Dealer reviewed inventory	Dealer certification	Handover preparation

VESSEL IDENTITY AND TITLE REVIEW

CONTROLLO	RISULTATO / NOTA	ESITO
ID veicolo	53790	VERIFICATO
Vessel type	Barca	VERIFICATO
Costruttore / marca	Delta	VERIFICATO
Hull identification / registration number	Da confermare alla consegna	IN ATTESA
Original registration papers	Available for dealer handover review	VERIFICATO

HULL, DECK AND EXTERIOR SURVEY

CONTROLLO	RISULTATO / NOTA	ESITO
Hull material	Non specificato	IN ATTESA
Hull visual inspection	Visible hull, gelcoat/paint and impact indicators reviewed	SUPERATO
Deck fittings and rails	Visible deck fittings, rails, cleats and access points checked	SUPERATO
Length / beam / draft	- / - / -	REGISTRATO
Current marina / location	European marina network	REGISTRATO

ENGINE, PROPULSION AND SYSTEMS

CONTROLLO	RISULTATO / NOTA	ESITO
Engine type	Non specificato	IN ATTESA
Engine power	Non specificato	IN ATTESA
Engine hours	Non specificato	IN ATTESA
Fuel type	Non specificato	IN ATTESA
Visible engine bay review	Leaks, corrosion indicators, belts, hoses and accessible systems reviewed	SUPERATO

ACCOMMODATION AND ONBOARD EQUIPMENT

CONTROLLO	RISULTATO / NOTA	ESITO
Cabins	Non specificato	IN ATTESA
Berths	Non specificato	IN ATTESA
Water capacity	Non specificato	IN ATTESA
Fuel capacity	Non specificato	IN ATTESA
Included equipment	Year: 2023 Electrical Equipment Shore Power Inlet: ✓ Generator: ✓ Electronics Depthsounder: ✓ Radar: ✓ Radar Detector: ✓ Navigation Center: ✓ Autopilot: ✓ Radio: ✓ Compass: ✓ GPS: ✓ Cockpit Speakers: ✓ VHF: ✓ AIS: ✓ Inside Equipment Bow Thruster: ✓ Electric Bilge Pump: ✓ Manual Bilge Pump: ✓ Air Conditioning: ✓ Electric Head: ✓ Heating: ✓ Refrigerator: ✓ Battery Charger: ✓ Outside Equipment Cockpit Shower: ✓ Electric Winch: ✓ Cockpit Cushions: ✓ Cockpit Table: ✓ Swimming Ladder: ✓ Gyroscopic Stabilizer: ✓	REVISIONATO

MARINE DELIVERY AND EXPORT READINESS

CONTROLLO	RISULTATO / NOTA	ESITO
Port delivery	Destination port delivery can be arranged where available	DISPONIBILE
Export support	Export eligible listing	PRONTO
Insurance handover note	Carrier/port handover should be documented before dispatch	RICHIESTO
Survey note	Marine survey scope recorded for customer handover	NOTA

LISTING EQUIPMENT AND NOTES

Year: 2023 Electrical Equipment Shore Power Inlet: ✓ Generator: ✓ Electronics Depthsounder: ✓ Radar: ✓ Radar Detector: ✓ Navigation Center: ✓ Autopilot: ✓ Radio: ✓ Compass: ✓ GPS: ✓ Cockpit Speakers: ✓ VHF: ✓ AIS: ✓ Inside Equipment Bow Thruster: ✓ Electric Bilge Pump: ✓ Manual Bilge Pump: ✓ Air Conditioning: ✓ Electric Head: ✓ Heating: ✓ Refrigerator: ✓ Battery Charger: ✓ Outside Equipment Cockpit Shower: ✓ Electric Winch: ✓ Cockpit Cushions: ✓ Cockpit Table: ✓ Swimming Ladder: ✓ Gyroscopic Stabilizer: ✓

INSPECTOR / HANDOVER SIGN-OFF

PREPARED BY	FINAL HANDOVER CONFIRMATION
MotoComply ApS inspection team	_____