

# Vehicle Inspection Report

Report no.: MC-IR-65130 | Vehicle ID: 65130 | Data di emissione: 2026-06-10

LISTING <b>2016 BMW R 1200 GS Triple Black  1. Hand  ESA, ASC, Koffer</b>	TIPO Motorcycle	STATO available
MAKE BMW	MODEL R 1200 GS	ANNO 2016
CONDIZIONE used	LOCATION Denmark	WARRANTY INFORMATION Inspection available before handover

<b>100%</b> Dealer reviewed inventory	<b>Review</b> Dealer certification	<b>Prepared</b> Handover preparation
--	---------------------------------------	---

## IDENTITY AND DOCUMENTATION

CHECKPOINT	FINDING / NOTE	RESULT
Vehicle ID	65130	VERIFIED
Vehicle type	Motorcycle	VERIFIED
VIN / chassis number	To be confirmed at handover	PENDING
Registration date	2016-04-01	REVIEWED
Original registration papers	Available for dealer handover review	VERIFIED

## MECHANICAL INSPECTION

CHECKPOINT	FINDING / NOTE	RESULT
Engine start and idle	Cold start, idle stability and visible leak check	PASSED
Engine size	1.170 cm <sup>3</sup>	VERIFIED
Transmission	Schaltgetriebe	VERIFIED
Powertrain response	Throttle response, clutch/drive engagement and abnormal noise check	PASSED
Cooling and fluids	Oil, coolant, brake fluid and visible hose condition checked	PASSED

## SAFETY AND ROADWORTHINESS

CHECKPOINT	FINDING / NOTE	RESULT
<b>Brakes</b>	Front/rear braking response and visible disc/pad condition checked	<b>PASSED</b>
<b>Tyres / wheels</b>	Tyre condition, wheel alignment indicators and visible rim damage checked	<b>PASSED</b>
<b>Suspension / steering</b>	Steering movement, fork/shock condition and bearing play check	<b>PASSED</b>
<b>Lights / horn / controls</b>	Operational control check completed	<b>PASSED</b>
<b>Mileage</b>	8396	<b>RECORDED</b>

## COSMETIC AND PREPARATION

CHECKPOINT	FINDING / NOTE	RESULT
<b>Exterior color</b>	Not specified	<b>PENDING</b>
<b>Body panels / frame</b>	Visible condition and preparation notes reviewed	<b>PASSED</b>
<b>Dealer preparation</b>	Prepared before customer handover	<b>VERIFIED</b>
<b>Dealer certification</b>	Dealer review required before final handover	<b>PENDING</b>

## DELIVERY READINESS

CHECKPOINT	FINDING / NOTE	RESULT
<b>Pickup readiness</b>	Customer pickup can be scheduled after admin confirmation	<b>READY</b>
<b>Road delivery</b>	Covered or trailer delivery can be arranged where available	<b>AVAILABLE</b>
<b>International delivery</b>	International export support available	<b>AVAILABLE</b>
<b>Handover documents</b>	Contract, invoice and inspection report prepared for customer review	<b>READY</b>

## LISTING EQUIPMENT AND NOTES

Make: BMW Model: R 1200 GS Version: Triple Black
1. Hand
ESA, ASC, Koffer Body type: Motorbike Condition: Used First registration: 04/2016 Mileage: 8.396 km Engine: 1.170 cm <sup>3</sup> Power: 92 kW (125 PS) Fuel: Benzin Transmission: Schaltgetriebe

## INSPECTOR / HANDOVER SIGN-OFF

PREPARED BY

MotoComply ApS inspection team

FINAL HANDOVER CONFIRMATION

\_\_\_\_\_

---

MotoComply ApS inspection report for Vehicle ID 65130. This report is generated from the current listing record and should be updated if listing data or inspection notes change.