RAPPORTO DI ISPEZIONE PROFESSIONALE

# Rapporto ispezione veicolo

**MotoComply ApS**
CVR 46320565
0045 98 89 89 98
info@motocomplydk.com

Rapporto n.: MC-IR-10579 | ID veicolo: 10579 | Data di emissione: 2026-10-30

| ANNUNCIO | TIPO | STATO |
|---|---|---|
| **2022 Ducati Panigale V4 S Black Forest** | Moto | Disponibile |
| **MARCA** | **MODELLO** | **ANNO** |
| Ducati | Panigale V4 S | 2022 |
| **CONDIZIONE** | **LOCALITÀ** | **INFORMAZIONI GARANZIA** |
| Usato | Denmark | Inspection available before handover |

| 100% | Review | Prepared |
|---|---|---|
| Dealer reviewed inventory | Dealer certification | Handover preparation |

## IDENTITÀ E DOCUMENTAZIONE

| CONTROLLO | RISULTATO / NOTA | ESITO |
|---|---|---|
| **ID veicolo** | 10579 | VERIFICATO |
| **Tipo veicolo** | Moto | VERIFICATO |
| **VIN / numero telaio** | Da confermare alla consegna | IN ATTESA |
| **Data registrazione** | 2022-05-01 | REVISIONATO |
| **Original registration papers** | Available for dealer handover review | VERIFICATO |

## ISPEZIONE MECCANICA

| CONTROLLO | RISULTATO / NOTA | ESITO |
|---|---|---|
| **Engine start and idle** | Cold start, idle stability and visible leak check | SUPERATO |
| **Engine size** | 1.103 cm³ | VERIFICATO |
| **Transmission** | inspection_report.value_transmission_Schaltgetriebe | VERIFICATO |
| **Powertrain response** | Throttle response, clutch/drive engagement and abnormal noise check | SUPERATO |
| **Cooling and fluids** | Oil, coolant, brake fluid and visible hose condition checked | SUPERATO |

## SICUREZZA E IDONEITÀ STRADALE

| CONTROLLO | RISULTATO / NOTA | ESITO |
|---|---|---|
| **Brakes** | Front/rear braking response and visible disc/pad condition checked | SUPERATO |
| **Tyres / wheels** | Tyre condition, wheel alignment indicators and visible rim damage checked | SUPERATO |
| **Suspension / steering** | Steering movement, fork/shock condition and bearing play check | SUPERATO |
| **Lights / horn / controls** | Operational control check completed | SUPERATO |
| **Mileage** | 3141 | REGISTRATO |

## ESTETICA E PREPARAZIONE

| CONTROLLO | RISULTATO / NOTA | ESITO |
|---|---|---|
| **Exterior color** | Non specificato | IN ATTESA |
| **Body panels / frame** | Visible condition and preparation notes reviewed | SUPERATO |
| **Dealer preparation** | Prepared before customer handover | VERIFICATO |
| **Dealer certification** | Dealer review required before final handover | IN ATTESA |

## PRONTEZZA CONSEGNA

| CONTROLLO | RISULTATO / NOTA | ESITO |
|---|---|---|
| **Pickup readiness** | Customer pickup can be scheduled after admin confirmation | PRONTO |
| **Road delivery** | Covered or trailer delivery can be arranged where available | DISPONIBILE |
| **International delivery** | International export support available | DISPONIBILE |
| **Handover documents** | Contract, invoice and inspection report prepared for customer review | PRONTO |

## LISTING EQUIPMENT AND NOTES

Make: Ducati Model: Panigale V4 S Version: Black Forest Body type: Motorbike Condition: Used First registration: 05/2022 Mileage: 3.141 km Engine: 1.103 cm³ Power: 159 kW (216 PS) Fuel: Benzin Transmission: Schaltgetriebe

## INSPECTOR / HANDOVER SIGN-OFF

| PREPARED BY | FINAL HANDOVER CONFIRMATION |
| --- | --- |
| MotoComply ApS inspection team | _____ |