RAPPORTO DI ISPEZIONE PROFESSIONALE

Rapporto ispezione veicolo

MotoComply ApS
CVR 46320565
0045 98 89 89 98
info@motocomplydk.com

Rapporto n.: MC-IR-50684 | ID veicolo: 50684 | Data di emissione: 2026-10-31

ANNUNCIO	TIPO	STATO
2026 Suzuki Hayabusa GSX - R 1300 Demo Fahrzeug in Menden be	Moto	Disponibile
MARCA	**MODELLO**	**ANNO**
Suzuki	Hayabusa	2026
CONDIZIONE	**LOCALITÀ**	**INFORMAZIONI GARANZIA**
Usato	Denmark	Inspection available before handover

100%	Review	Prepared
Dealer reviewed inventory	Dealer certification	Handover preparation

IDENTITÀ E DOCUMENTAZIONE

CONTROLLO	RISULTATO / NOTA	ESITO
ID veicolo	50684	VERIFICATO
Tipo veicolo	Moto	VERIFICATO
VIN / numero telaio	Da confermare alla consegna	IN ATTESA
Data registrazione	Non fornito	IN ATTESA
Original registration papers	Available for dealer handover review	VERIFICATO

ISPEZIONE MECCANICA

CONTROLLO	RISULTATO / NOTA	ESITO
Engine start and idle	Cold start, idle stability and visible leak check	SUPERATO
Engine size	1.340 cm³	VERIFICATO
Transmission	inspection_report.value_transmission_Schaltgetriebe	VERIFICATO
Powertrain response	Throttle response, clutch/drive engagement and abnormal noise check	SUPERATO
Cooling and fluids	Oil, coolant, brake fluid and visible hose condition checked	SUPERATO

SICUREZZA E IDONEITÀ STRADALE

CONTROLLO	RISULTATO / NOTA	ESITO
Brakes	Front/rear braking response and visible disc/pad condition checked	SUPERATO
Tyres / wheels	Tyre condition, wheel alignment indicators and visible rim damage checked	SUPERATO
Suspension / steering	Steering movement, fork/shock condition and bearing play check	SUPERATO
Lights / horn / controls	Operational control check completed	SUPERATO
Mileage	10	REGISTRATO

ESTETICA E PREPARAZIONE

CONTROLLO	RISULTATO / NOTA	ESITO
Exterior color	Non specificato	IN ATTESA
Body panels / frame	Visible condition and preparation notes reviewed	SUPERATO
Dealer preparation	Prepared before customer handover	VERIFICATO
Dealer certification	Dealer review required before final handover	IN ATTESA

PRONTEZZA CONSEGNA

CONTROLLO	RISULTATO / NOTA	ESITO
Pickup readiness	Customer pickup can be scheduled after admin confirmation	PRONTO
Road delivery	Covered or trailer delivery can be arranged where available	DISPONIBILE
International delivery	International export support available	DISPONIBILE
Handover documents	Contract, invoice and inspection report prepared for customer review	PRONTO

LISTING EQUIPMENT AND NOTES

Make: Suzuki Model: Hayabusa Version: GSX - R 1300 Demo Fahrzeug in Menden be Body type: Supersport Condition: Used Mileage: 10 km Engine: 1.340 cm³ Power: 140 kW (190 PS) Fuel: Benzin Transmission: Schaltgetriebe

INSPECTOR / HANDOVER SIGN-OFF

PREPARED BY	FINAL HANDOVER CONFIRMATION
MotoComply ApS inspection team	_____