PROFESSIONEEL INSPECTIERAPPORT

# Inspectierapport boot / jacht

**MotoComply ApS**
CVR 46320565
0045 98 89 89 98
info@motocomplydk.com

Rapportnr.: MC-IR-53790 | Voertuig-ID: 53790 | Uitgiftedatum: 2026-10-31

| ADVERTENTIE | TYPE | STATUS |
|---|---|---|
| **2023 Delta Powerboats 33 Coupe** | Boot | Beschikbaar |
| **BOUWER / MERK** | **MODEL** | **BOUWJAAR** |
| Delta | Powerboats 33 Coupe | 2023 |
| **CONDITIE** | **LOCATIE** | **GARANTIE-INFORMATIE** |
| Gebruikt | European marina network | Inspection available before handover |

| 100% | Review | Prepared |
|---|---|---|
| Dealer reviewed inventory | Dealer certification | Handover preparation |

## VESSEL IDENTITY AND TITLE REVIEW

| CONTROLEPUNT | BEVINDING / NOTITIE | RESULTAAT |
|---|---|---|
| **Voertuig-ID** | 53790 | GEVERIFIEERD |
| **Vessel type** | Boot | GEVERIFIEERD |
| **Bouwer / merk** | Delta | GEVERIFIEERD |
| **Hull identification / registration number** | Te bevestigen bij overdracht | IN AFWACHTING |
| **Original registration papers** | Available for dealer handover review | GEVERIFIEERD |

## HULL, DECK AND EXTERIOR SURVEY

| CONTROLEPUNT | BEVINDING / NOTITIE | RESULTAAT |
|---|---|---|
| **Hull material** | Niet gespecificeerd | IN AFWACHTING |
| **Hull visual inspection** | Visible hull, gelcoat/paint and impact indicators reviewed | GOEDGEKEURD |
| **Deck fittings and rails** | Visible deck fittings, rails, cleats and access points checked | GOEDGEKEURD |
| **Length / beam / draft** | - / - / - | VASTGELEGD |
| **Current marina / location** | European marina network | VASTGELEGD |

## ENGINE, PROPULSION AND SYSTEMS

| CONTROLEPUNT | BEVINDING / NOTITIE | RESULTAAT |
|---|---|---|
| **Engine type** | Niet gespecificeerd | IN AFWACHTING |
| **Engine power** | Niet gespecificeerd | IN AFWACHTING |
| **Engine hours** | Niet gespecificeerd | IN AFWACHTING |
| **Fuel type** | Niet gespecificeerd | IN AFWACHTING |
| **Visible engine bay review** | Leaks, corrosion indicators, belts, hoses and accessible systems reviewed | GOEDGEKEURD |

## ACCOMMODATION AND ONBOARD EQUIPMENT

| CONTROLEPUNT | BEVINDING / NOTITIE | RESULTAAT |
|---|---|---|
| **Cabins** | Niet gespecificeerd | IN AFWACHTING |
| **Berths** | Niet gespecificeerd | IN AFWACHTING |
| **Water capacity** | Niet gespecificeerd | IN AFWACHTING |
| **Fuel capacity** | Niet gespecificeerd | IN AFWACHTING |
| **Included equipment** | Year: 2023 Electrical Equipment Shore Power Inlet: ✓ Generator: ✓ Electronics Depthsounder: ✓ Radar: ✓ Radar Detector: ✓ Navigation Center: ✓ Autopilot: ✓ Radio: ✓ Compass: ✓ GPS: ✓ Cockpit Speakers: ✓ VHF: ✓ AIS: ✓ Inside Equipment Bow Thruster: ✓ Electric Bilge Pump: ✓ Manual Bilge Pump: ✓ Air Conditioning: ✓ Electric Head: ✓ Heating: ✓ Refrigerator: ✓ Battery Charger: ✓ Outside Equipment Cockpit Shower: ✓ Electric Winch: ✓ Cockpit Cushions: ✓ Cockpit Table: ✓ Swimming Ladder: ✓ Gyroscopic Stabilizer: ✓ | BEOORDEELD |

## MARINE DELIVERY AND EXPORT READINESS

| CONTROLEPUNT | BEVINDING / NOTITIE | RESULTAAT |
|---|---|---|
| **Port delivery** | Destination port delivery can be arranged where available | BESCHIKBAAR |
| **Export support** | Export eligible listing | GEREED |
| **Insurance handover note** | Carrier/port handover should be documented before dispatch | VEREIST |
| **Survey note** | Marine survey scope recorded for customer handover | ADVIES |

## LISTING EQUIPMENT AND NOTES

Year: 2023 Electrical Equipment Shore Power Inlet: ✓ Generator: ✓ Electronics Depthsounder: ✓ Radar: ✓ Radar Detector: ✓ Navigation Center: ✓ Autopilot: ✓ Radio: ✓ Compass: ✓ GPS: ✓ Cockpit Speakers: ✓ VHF: ✓ AIS: ✓ Inside Equipment Bow Thruster: ✓ Electric Bilge Pump: ✓ Manual Bilge Pump: ✓ Air Conditioning: ✓ Electric Head: ✓ Heating: ✓ Refrigerator: ✓ Battery Charger: ✓ Outside Equipment Cockpit Shower: ✓ Electric Winch: ✓ Cockpit Cushions: ✓ Cockpit Table: ✓ Swimming Ladder: ✓ Gyroscopic Stabilizer: ✓

## INSPECTOR / HANDOVER SIGN-OFF

| PREPARED BY | FINAL HANDOVER CONFIRMATION |
| --- | --- |
| MotoComply ApS inspection team | _____ |