

# Vehicle Inspection Report

Report no.: MC-IR-92027 | Vehicle ID: 92027 | Uitgiftedatum: 2026-06-10

LISTING <b>2017 Harley-Davidson XL 1200 X Forty Eight 48 ABS  Umbau  TOP Zustand!</b>	TYPE Motorcycle	STATUS available
MAKE Harley-Davidson	MODEL XL 1200	JAAR 2017
STAAT used	LOCATION Denmark	WARRANTY INFORMATION Inspection available before handover

<b>100%</b> Dealer reviewed inventory	<b>Review</b> Dealer certification	<b>Prepared</b> Handover preparation
--	---------------------------------------	---

## IDENTITY AND DOCUMENTATION

CHECKPOINT	FINDING / NOTE	RESULT
Vehicle ID	92027	VERIFIED
Vehicle type	Motorcycle	VERIFIED
VIN / chassis number	To be confirmed at handover	PENDING
Registration date	2017-08-01	REVIEWED
Original registration papers	Available for dealer handover review	VERIFIED

## MECHANICAL INSPECTION

CHECKPOINT	FINDING / NOTE	RESULT
Engine start and idle	Cold start, idle stability and visible leak check	PASSED
Engine size	1.202 cm <sup>3</sup>	VERIFIED
Transmission	Schaltgetriebe	VERIFIED
Powertrain response	Throttle response, clutch/drive engagement and abnormal noise check	PASSED
Cooling and fluids	Oil, coolant, brake fluid and visible hose condition checked	PASSED

## SAFETY AND ROADWORTHINESS

CHECKPOINT	FINDING / NOTE	RESULT
<b>Brakes</b>	Front/rear braking response and visible disc/pad condition checked	<b>PASSED</b>
<b>Tyres / wheels</b>	Tyre condition, wheel alignment indicators and visible rim damage checked	<b>PASSED</b>
<b>Suspension / steering</b>	Steering movement, fork/shock condition and bearing play check	<b>PASSED</b>
<b>Lights / horn / controls</b>	Operational control check completed	<b>PASSED</b>
<b>Mileage</b>	2560	<b>RECORDED</b>

## COSMETIC AND PREPARATION

CHECKPOINT	FINDING / NOTE	RESULT
<b>Exterior color</b>	Not specified	<b>PENDING</b>
<b>Body panels / frame</b>	Visible condition and preparation notes reviewed	<b>PASSED</b>
<b>Dealer preparation</b>	Prepared before customer handover	<b>VERIFIED</b>
<b>Dealer certification</b>	Dealer review required before final handover	<b>PENDING</b>

## DELIVERY READINESS

CHECKPOINT	FINDING / NOTE	RESULT
<b>Pickup readiness</b>	Customer pickup can be scheduled after admin confirmation	<b>READY</b>
<b>Road delivery</b>	Covered or trailer delivery can be arranged where available	<b>AVAILABLE</b>
<b>International delivery</b>	International export support available	<b>AVAILABLE</b>
<b>Handover documents</b>	Contract, invoice and inspection report prepared for customer review	<b>READY</b>

## LISTING EQUIPMENT AND NOTES

Make: Harley-Davidson Model: XL 1200 Version: X Forty Eight 48 ABS
Umbau
TOP Zustand! Body type: Motorbike Condition: Used First registration: 08/2017 Mileage: 2.560 km Engine: 1.202 cm <sup>3</sup> Power: 49 kW (67 PS) Fuel: Benzin Transmission: Schaltgetriebe

## INSPECTOR / HANDOVER SIGN-OFF

PREPARED BY

MotoComply ApS inspection team

FINAL HANDOVER CONFIRMATION

\_\_\_\_\_

---

MotoComply ApS inspection report for Vehicle ID 92027. This report is generated from the current listing record and should be updated if listing data or inspection notes change.