

Vehicle Inspection Report

Report no.: MC-IR-50684 | Vehicle ID: 50684 | Uitgiftedatum: 2026-06-10

LISTING 2026 Suzuki Hayabusa GSX - R 1300 Demo Fahrzeug in Menden be	TYPE Motorcycle	STATUS available
MAKE Suzuki	MODEL Hayabusa	JAAR 2026
STAAT used	LOCATION Denmark	WARRANTY INFORMATION Inspection available before handover

100% Dealer reviewed inventory	Review Dealer certification	Prepared Handover preparation
--	---------------------------------------	---

IDENTITY AND DOCUMENTATION

CHECKPOINT	FINDING / NOTE	RESULT
Vehicle ID	50684	VERIFIED
Vehicle type	Motorcycle	VERIFIED
VIN / chassis number	To be confirmed at handover	PENDING
Registration date	Not supplied	PENDING
Original registration papers	Available for dealer handover review	VERIFIED

MECHANICAL INSPECTION

CHECKPOINT	FINDING / NOTE	RESULT
Engine start and idle	Cold start, idle stability and visible leak check	PASSED
Engine size	1.340 cm ³	VERIFIED
Transmission	Schaltgetriebe	VERIFIED
Powertrain response	Throttle response, clutch/drive engagement and abnormal noise check	PASSED
Cooling and fluids	Oil, coolant, brake fluid and visible hose condition checked	PASSED

SAFETY AND ROADWORTHINESS

CHECKPOINT	FINDING / NOTE	RESULT
Brakes	Front/rear braking response and visible disc/pad condition checked	PASSED
Tyres / wheels	Tyre condition, wheel alignment indicators and visible rim damage checked	PASSED
Suspension / steering	Steering movement, fork/shock condition and bearing play check	PASSED
Lights / horn / controls	Operational control check completed	PASSED
Mileage	10	RECORDED

COSMETIC AND PREPARATION

CHECKPOINT	FINDING / NOTE	RESULT
Exterior color	Not specified	PENDING
Body panels / frame	Visible condition and preparation notes reviewed	PASSED
Dealer preparation	Prepared before customer handover	VERIFIED
Dealer certification	Dealer review required before final handover	PENDING

DELIVERY READINESS

CHECKPOINT	FINDING / NOTE	RESULT
Pickup readiness	Customer pickup can be scheduled after admin confirmation	READY
Road delivery	Covered or trailer delivery can be arranged where available	AVAILABLE
International delivery	International export support available	AVAILABLE
Handover documents	Contract, invoice and inspection report prepared for customer review	READY

LISTING EQUIPMENT AND NOTES

Make: Suzuki Model: Hayabusa Version: GSX - R 1300 Demo Fahrzeug in Menden be Body type: Supersport Condition: Used
Mileage: 10 km Engine: 1.340 cm³ Power: 140 kW (190 PS) Fuel: Benzin Transmission: Schaltgetriebe

INSPECTOR / HANDOVER SIGN-OFF

PREPARED BY MotoComply ApS inspection team	FINAL HANDOVER CONFIRMATION _____
---	--------------------------------------