

Marine / Yacht Inspection Report

Report no.: MC-IR-38710 | Vehicle ID: 38710 | Uitgiftedatum: 2026-06-10

| | | |
|--|-------------------------------------|--|
| LISTING 2021 Beneteau Oceanis 40.1 | TYPE Boat | STATUS available |
| BUILDER / MAKE Beneteau | MODEL Oceanis 40.1 | JAAR 2021 |
| STAAT used | LOCATION European marina network | WARRANTY INFORMATION Inspection available before handover |

| | | |
|--|---------------------------------------|---|
| 100% Dealer reviewed inventory | Review Dealer certification | Prepared Handover preparation |
|--|---------------------------------------|---|

VESSEL IDENTITY AND TITLE REVIEW

| CHECKPOINT | FINDING / NOTE | RESULT |
|---|--------------------------------------|----------|
| Vehicle ID | 38710 | VERIFIED |
| Vessel type | Boat | VERIFIED |
| Builder / make | Beneteau | VERIFIED |
| Hull identification / registration number | To be confirmed at handover | PENDING |
| Original registration papers | Available for dealer handover review | VERIFIED |

HULL, DECK AND EXTERIOR SURVEY

| CHECKPOINT | FINDING / NOTE | RESULT |
|---------------------------|--|----------|
| Hull material | Not specified | PENDING |
| Hull visual inspection | Visible hull, gelcoat/paint and impact indicators reviewed | PASSED |
| Deck fittings and rails | Visible deck fittings, rails, cleats and access points checked | PASSED |
| Length / beam / draft | - / - / - | RECORDED |
| Current marina / location | European marina network | RECORDED |

ENGINE, PROPULSION AND SYSTEMS

| CHECKPOINT | FINDING / NOTE | RESULT |
|---------------------------|---|---------|
| Engine type | Not specified | PENDING |
| Engine power | Not specified | PENDING |
| Engine hours | Not specified | PENDING |
| Fuel type | Not specified | PENDING |
| Visible engine bay review | Leaks, corrosion indicators, belts, hoses and accessible systems reviewed | PASSED |

ACCOMMODATION AND ONBOARD EQUIPMENT

| CHECKPOINT | FINDING / NOTE | RESULT |
|--------------------|----------------|----------|
| Cabins | Not specified | PENDING |
| Berths | Not specified | PENDING |
| Water capacity | Not specified | PENDING |
| Fuel capacity | Not specified | PENDING |
| Included equipment | Year: 2021 | REVIEWED |

MARINE DELIVERY AND EXPORT READINESS

| CHECKPOINT | FINDING / NOTE | RESULT |
|-------------------------|--|-----------|
| Port delivery | Destination port delivery can be arranged where available | AVAILABLE |
| Export support | Export eligible listing | READY |
| Insurance handover note | Carrier/port handover should be documented before dispatch | REQUIRED |
| Survey note | Marine survey scope recorded for customer handover | ADVISORY |

LISTING EQUIPMENT AND NOTES

| |
|------------|
| Year: 2021 |
|------------|

INSPECTOR / HANDOVER SIGN-OFF

| | |
|---|--------------------------------------|
| PREPARED BY MotoComply ApS inspection team | FINAL HANDOVER CONFIRMATION _____ |
|---|--------------------------------------|