

# Marine / Yacht Inspection Report

Report no.: MC-IR-92065 | Vehicle ID: 92065 | Data wystawienia: 2026-06-10

LISTING <b>2026 Mega Yacht Custom</b>	TYP Yacht	STATUS available
BUILDER / MAKE Mega	MODEL Yacht Custom	ROK 2026
STAN used	LOCATION European marina network	WARRANTY INFORMATION Inspection available before handover

<b>100%</b> Dealer reviewed inventory	<b>Review</b> Dealer certification	<b>Prepared</b> Handover preparation
--	---------------------------------------	---

## VESSEL IDENTITY AND TITLE REVIEW

CHECKPOINT	FINDING / NOTE	RESULT
Vehicle ID	92065	VERIFIED
Vessel type	Yacht	VERIFIED
Builder / make	Mega	VERIFIED
Hull identification / registration number	To be confirmed at handover	PENDING
Original registration papers	Available for dealer handover review	VERIFIED

## HULL, DECK AND EXTERIOR SURVEY

CHECKPOINT	FINDING / NOTE	RESULT
Hull material	Not specified	PENDING
Hull visual inspection	Visible hull, gelcoat/paint and impact indicators reviewed	PASSED
Deck fittings and rails	Visible deck fittings, rails, cleats and access points checked	PASSED
Length / beam / draft	- / - / -	RECORDED
Current marina / location	European marina network	RECORDED

## ENGINE, PROPULSION AND SYSTEMS

CHECKPOINT	FINDING / NOTE	RESULT
Engine type	Not specified	PENDING
Engine power	Not specified	PENDING
Engine hours	Not specified	PENDING
Fuel type	Not specified	PENDING
Visible engine bay review	Leaks, corrosion indicators, belts, hoses and accessible systems reviewed	PASSED

## ACCOMMODATION AND ONBOARD EQUIPMENT

CHECKPOINT	FINDING / NOTE	RESULT
Cabins	Not specified	PENDING
Berths	Not specified	PENDING
Water capacity	Not specified	PENDING
Fuel capacity	Not specified	PENDING
Included equipment	Year: 2026 Electrical Equipment Shore Power Inlet: ✓ Generator: ✓ Inverter: ✓ Electronics Depthsounder: ✓ Radar: ✓ Log-Speedometer: ✓ Wind Speed and Direction: ✓ Computer: ✓ Repeater(s): ✓ TV Set: ✓ Navigation Center: ✓ Plotter: ✓ Autopilot: ✓ Radio: ✓ Compass: ✓ GPS: ✓ Cockpit Speakers: ✓ VHF: ✓ Inside Equipment Stern Thruster: ✓ Dishwasher: ✓ Bow Thruster: ✓ Washing Machine: ✓ Electric Bilge Pump: ✓ Oven: ✓ Manual Bilge Pump: ✓ Microwave Oven: ✓ Air Compressor: ✓ Air Conditioning: ✓ Electric Head: ✓ Heating: ✓ Hot Water: ✓ Refrigerator: ✓ Fresh Water Maker: ✓ Deep Freezer: ✓ Sea Water Pump: ✓ Battery Charger: ✓	REVIEWED

## MARINE DELIVERY AND EXPORT READINESS

CHECKPOINT	FINDING / NOTE	RESULT
Port delivery	Destination port delivery can be arranged where available	AVAILABLE
Export support	Export eligible listing	READY
Insurance handover note	Carrier/port handover should be documented before dispatch	REQUIRED
Survey note	Marine survey scope recorded for customer handover	ADVISORY

## LISTING EQUIPMENT AND NOTES

Year: 2026 Electrical Equipment Shore Power Inlet: ✓ Generator: ✓ Inverter: ✓ Electronics Depthsounder: ✓ Radar: ✓ Log-Speedometer: ✓ Wind Speed and Direction: ✓ Computer: ✓ Repeater(s): ✓ TV Set: ✓ Navigation Center: ✓ Plotter: ✓ Autopilot: ✓ Radio: ✓ Compass: ✓ GPS: ✓ Cockpit Speakers: ✓ VHF: ✓ Inside Equipment Stern Thruster: ✓ Dishwasher: ✓ Bow Thruster: ✓ Washing Machine: ✓ Electric Bilge Pump: ✓ Oven: ✓ Manual Bilge Pump: ✓ Microwave Oven: ✓ Air Compressor: ✓ Air Conditioning: ✓ Electric Head: ✓ Heating: ✓ Hot Water: ✓ Refrigerator: ✓ Fresh Water Maker: ✓ Deep Freezer: ✓ Sea Water Pump: ✓ Battery Charger: ✓

## INSPECTOR / HANDOVER SIGN-OFF

PREPARED BY

MotoComply ApS inspection team

FINAL HANDOVER CONFIRMATION

\_\_\_\_\_

MotoComply ApS inspection report for Vehicle ID 92065. This report is generated from the current listing record and should be updated if listing data or inspection notes change.