

# Vehicle Inspection Report

Report no.: MC-IR-45583 | Vehicle ID: 45583 | Data de emissão: 2026-06-10

|                                   |                           |  |
|-----------------------------------|---------------------------|--|
| LISTING<br><b>HARLEY-DAVIDSON</b> | TIPO<br>Motorcycle        | ESTADO<br>available                                |
| MAKE<br>Harley-Davidson           | MODEL<br>Erbacher The One | ANO<br>2014  |
| CONDIÇÃO<br>excellent             | LOCATION<br>Denmark       | WARRANTY INFORMATION<br>12 Months Limited Warranty |

|  |  |   |
|--|--|---|
| <b>100%</b><br>Dealer reviewed inventory | <b>Certified</b><br>Dealer certification | <b>Serviced</b><br>Handover preparation |
|--|--|---|

## IDENTITY AND DOCUMENTATION

| CHECKPOINT                   | FINDING / NOTE                       | RESULT   |
|------------------------------|--------------------------------------|----------|
| Vehicle ID                   | 45583                                | VERIFIED |
| Vehicle type                 | Motorcycle                           | VERIFIED |
| VIN / chassis number         | To be confirmed at handover          | PENDING  |
| Registration date            | Not supplied                         | PENDING  |
| Original registration papers | Available for dealer handover review | VERIFIED |

## MECHANICAL INSPECTION

| CHECKPOINT            | FINDING / NOTE  | RESULT   |
|-----------------------|---|----------|
| Engine start and idle | Cold start, idle stability and visible leak check                   | PASSED   |
| Engine size           | 2000  | VERIFIED |
| Transmission          | manual  | VERIFIED |
| Powertrain response   | Throttle response, clutch/drive engagement and abnormal noise check | PASSED   |
| Cooling and fluids    | Oil, coolant, brake fluid and visible hose condition checked        | PASSED   |

## SAFETY AND ROADWORTHINESS

| CHECKPOINT               | FINDING / NOTE  | RESULT   |
|--------------------------|---|----------|
| Brakes                   | Front/rear braking response and visible disc/pad condition checked        | PASSED   |
| Tyres / wheels           | Tyre condition, wheel alignment indicators and visible rim damage checked | PASSED   |
| Suspension / steering    | Steering movement, fork/shock condition and bearing play check            | PASSED   |
| Lights / horn / controls | Operational control check completed                                       | PASSED   |
| Mileage                  | 2207  | RECORDED |

## COSMETIC AND PREPARATION

| CHECKPOINT           | FINDING / NOTE                                   | RESULT   |
|----------------------|--|----------|
| Exterior color       | Black  | RECORDED |
| Body panels / frame  | Visible condition and preparation notes reviewed | PASSED   |
| Dealer preparation   | Recently serviced before listing                 | VERIFIED |
| Dealer certification | Dealer certified listing                         | VERIFIED |

## DELIVERY READINESS

| CHECKPOINT             | FINDING / NOTE   | RESULT    |
|------------------------|--|-----------|
| Pickup readiness       | Customer pickup can be scheduled after admin confirmation            | READY     |
| Road delivery          | Covered or trailer delivery can be arranged where available          | AVAILABLE |
| International delivery | Available by custom quote  | AVAILABLE |
| Handover documents     | Contract, invoice and inspection report prepared for customer review | READY     |

## LISTING EQUIPMENT AND NOTES

|                        |
|------------------------|
| Dealer certified       |
| Recently serviced      |
| Secure contract        |
| Complimentary delivery |

## INSPECTOR / HANDOVER SIGN-OFF

PREPARED BY

MotoComply ApS inspection team

FINAL HANDOVER CONFIRMATION

\_\_\_\_\_

---

MotoComply ApS inspection report for Vehicle ID 45583. This report is generated from the current listing record and should be updated if listing data or inspection notes change.