

# Vehicle Inspection Report

Report no.: MC-IR-62419 | Vehicle ID: 62419 | Data de emissão: 2026-06-10

LISTING <b>2010 CAN-AM Renegade Renegade 800R 4x4</b>	TIPO Quad	ESTADO available
MAKE CAN-AM	MODEL Renegade	ANO 2010
CONDIÇÃO used	LOCATION Denmark	WARRANTY INFORMATION Inspection available before handover

<b>100%</b> Dealer reviewed inventory	<b>Review</b> Dealer certification	<b>Prepared</b> Handover preparation
--	---------------------------------------	---

## IDENTITY AND DOCUMENTATION

CHECKPOINT	FINDING / NOTE	RESULT
Vehicle ID	62419	VERIFIED
Vehicle type	Quad	VERIFIED
VIN / chassis number	To be confirmed at handover	PENDING
Registration date	2010-05-01	REVIEWED
Original registration papers	Available for dealer handover review	VERIFIED

## MECHANICAL INSPECTION

CHECKPOINT	FINDING / NOTE	RESULT
Engine start and idle	Cold start, idle stability and visible leak check	PASSED
Engine size	806	VERIFIED
Transmission	automatic-stepless	VERIFIED
Powertrain response	Throttle response, clutch/drive engagement and abnormal noise check	PASSED
Cooling and fluids	Oil, coolant, brake fluid and visible hose condition checked	PASSED

## SAFETY AND ROADWORTHINESS

CHECKPOINT	FINDING / NOTE	RESULT
Brakes	Front/rear braking response and visible disc/pad condition checked	PASSED
Tyres / wheels	Tyre condition, wheel alignment indicators and visible rim damage checked	PASSED
Suspension / steering	Steering movement, fork/shock condition and bearing play check	PASSED
Lights / horn / controls	Operational control check completed	PASSED
Mileage	690	RECORDED

## COSMETIC AND PREPARATION

CHECKPOINT	FINDING / NOTE	RESULT
Exterior color	yellow	RECORDED
Body panels / frame	Visible condition and preparation notes reviewed	PASSED
Dealer preparation	Prepared before customer handover	VERIFIED
Dealer certification	Dealer review required before final handover	PENDING

## DELIVERY READINESS

CHECKPOINT	FINDING / NOTE	RESULT
Pickup readiness	Customer pickup can be scheduled after admin confirmation	READY
Road delivery	Covered or trailer delivery can be arranged where available	AVAILABLE
International delivery	International export support available	AVAILABLE
Handover documents	Contract, invoice and inspection report prepared for customer review	READY

## LISTING EQUIPMENT AND NOTES

Make: CAN-AM Model: Renegade Version: Renegade 800R 4x4 Body type: atv-quad Condition: Used Year: 2010 First registration: 2010-05-01 Mileage: 690 Engine: 806 Power: 19 Fuel: petrol Transmission: automatic-stepless Color: yellow Accident history: False

## INSPECTOR / HANDOVER SIGN-OFF

PREPARED BY MotoComply ApS inspection team	FINAL HANDOVER CONFIRMATION _____
---	--------------------------------------

---

MotoComply ApS inspection report for Vehicle ID 62419. This report is generated from the current listing record and should be updated if listing data or inspection notes change.