

# Vehicle Inspection Report

Report no.: MC-IR-29406 | Vehicle ID: 29406 | Data de emissão: 2026-06-10

LISTING <b>2019 MV AGUSTA Dragster Dragster 800 RR ABS Custom</b>	TIPO Motorcycle	ESTADO available
MAKE MV AGUSTA	MODEL Dragster	ANO 2019
CONDIÇÃO used	LOCATION Denmark	WARRANTY INFORMATION Inspection available before handover

<b>100%</b> Dealer reviewed inventory	<b>Review</b> Dealer certification	<b>Prepared</b> Handover preparation
--	---------------------------------------	---

## IDENTITY AND DOCUMENTATION

CHECKPOINT	FINDING / NOTE	RESULT
Vehicle ID	29406	VERIFIED
Vehicle type	Motorcycle	VERIFIED
VIN / chassis number	To be confirmed at handover	PENDING
Registration date	2019-02-01	REVIEWED
Original registration papers	Available for dealer handover review	VERIFIED

## MECHANICAL INSPECTION

CHECKPOINT	FINDING / NOTE	RESULT
Engine start and idle	Cold start, idle stability and visible leak check	PASSED
Engine size	798	VERIFIED
Transmission	manual	VERIFIED
Powertrain response	Throttle response, clutch/drive engagement and abnormal noise check	PASSED
Cooling and fluids	Oil, coolant, brake fluid and visible hose condition checked	PASSED

## SAFETY AND ROADWORTHINESS

CHECKPOINT	FINDING / NOTE	RESULT
Brakes	Front/rear braking response and visible disc/pad condition checked	PASSED
Tyres / wheels	Tyre condition, wheel alignment indicators and visible rim damage checked	PASSED
Suspension / steering	Steering movement, fork/shock condition and bearing play check	PASSED
Lights / horn / controls	Operational control check completed	PASSED
Mileage	1747	RECORDED

## COSMETIC AND PREPARATION

CHECKPOINT	FINDING / NOTE	RESULT
Exterior color	black	RECORDED
Body panels / frame	Visible condition and preparation notes reviewed	PASSED
Dealer preparation	Prepared before customer handover	VERIFIED
Dealer certification	Dealer review required before final handover	PENDING

## DELIVERY READINESS

CHECKPOINT	FINDING / NOTE	RESULT
Pickup readiness	Customer pickup can be scheduled after admin confirmation	READY
Road delivery	Covered or trailer delivery can be arranged where available	AVAILABLE
International delivery	International export support available	AVAILABLE
Handover documents	Contract, invoice and inspection report prepared for customer review	READY

## LISTING EQUIPMENT AND NOTES

Make: MV AGUSTA Model: Dragster Version: Dragster 800 RR ABS Custom Body type: street-bike Condition: Used Year: 2019 First registration: 2019-02-01 Mileage: 1747 Engine: 798 Power: 140 Fuel: petrol Transmission: manual Color: black Accident history: False

## INSPECTOR / HANDOVER SIGN-OFF

PREPARED BY MotoComply ApS inspection team	FINAL HANDOVER CONFIRMATION _____
---	--------------------------------------

---

MotoComply ApS inspection report for Vehicle ID 29406. This report is generated from the current listing record and should be updated if listing data or inspection notes change.