

Marine / Yacht Inspection Report

Report no.: MC-IR-14331 | Vehicle ID: 14331 | Dátum vystavenia: 2026-06-10

LISTING 2010 American Tug 41	TYP Boat	STAV available
BUILDER / MAKE American	MODEL Tug 41	ROK 2010
STAV used	LOCATION European marina network	WARRANTY INFORMATION Inspection available before handover

100% Dealer reviewed inventory	Review Dealer certification	Prepared Handover preparation
--	---------------------------------------	---

VESSEL IDENTITY AND TITLE REVIEW

CHECKPOINT	FINDING / NOTE	RESULT
Vehicle ID	14331	VERIFIED
Vessel type	Boat	VERIFIED
Builder / make	American	VERIFIED
Hull identification / registration number	To be confirmed at handover	PENDING
Original registration papers	Available for dealer handover review	VERIFIED

HULL, DECK AND EXTERIOR SURVEY

CHECKPOINT	FINDING / NOTE	RESULT
Hull material	Not specified	PENDING
Hull visual inspection	Visible hull, gelcoat/paint and impact indicators reviewed	PASSED
Deck fittings and rails	Visible deck fittings, rails, cleats and access points checked	PASSED
Length / beam / draft	- / - / -	RECORDED
Current marina / location	European marina network	RECORDED

ENGINE, PROPULSION AND SYSTEMS

CHECKPOINT	FINDING / NOTE	RESULT
Engine type	Not specified	PENDING
Engine power	Not specified	PENDING
Engine hours	Not specified	PENDING
Fuel type	Not specified	PENDING
Visible engine bay review	Leaks, corrosion indicators, belts, hoses and accessible systems reviewed	PASSED

ACCOMMODATION AND ONBOARD EQUIPMENT

CHECKPOINT	FINDING / NOTE	RESULT
Cabins	Not specified	PENDING
Berths	Not specified	PENDING
Water capacity	Not specified	PENDING
Fuel capacity	Not specified	PENDING
Included equipment	Year: 2010 Electrical Equipment Shore Power Inlet: ✓ Generator: Northern Light 7 kw, sound shield Inverter: ✓ Electronics Depthsounder: ✓ Radar: ✓ Log-Speedometer: ✓ Repeater(s): ✓ TV Set: ✓ Plotter: ✓ Autopilot: ✓ Radio: ✓ Compass: ✓ GPS: ✓ Cockpit Speakers: ✓ VHF: ✓ Inside Equipment Stern Thruster: ✓ Dishwasher: ✓ Bow Thruster: 8 hp twin propeller Washing Machine: ✓ Electric Bilge Pump: ✓ Oven: ✓ Manual Bilge Pump: ✓ Microwave Oven: ✓ Air Conditioning: ✓ Electric Head: ✓ Heating: ✓ Hot Water: ✓ Refrigerator: ✓ Deep Freezer: ✓ Battery Charger: ✓ Outside Equipment Teak Cockpit: ✓ Teak Sidedecks: ✓ Cockpit Table: ✓ Swimming Ladder: ✓	REVIEWED

MARINE DELIVERY AND EXPORT READINESS

CHECKPOINT	FINDING / NOTE	RESULT
Port delivery	Destination port delivery can be arranged where available	AVAILABLE
Export support	Export eligible listing	READY
Insurance handover note	Carrier/port handover should be documented before dispatch	REQUIRED
Survey note	Marine survey scope recorded for customer handover	ADVISORY

LISTING EQUIPMENT AND NOTES

Year: 2010 Electrical Equipment Shore Power Inlet: ✓ Generator: Northern Light 7 kw, sound shield Inverter: ✓ Electronics
Depthsounder: ✓ Radar: ✓ Log-Speedometer: ✓ Repeater(s): ✓ TV Set: ✓ Plotter: ✓ Autopilot: ✓ Radio: ✓ Compass: ✓ GPS: ✓
Cockpit Speakers: ✓ VHF: ✓ Inside Equipment Stern Thruster: ✓ Dishwasher: ✓ Bow Thruster: 8 hp twin propeller Washing
Machine: ✓ Electric Bilge Pump: ✓ Oven: ✓ Manual Bilge Pump: ✓ Microwave Oven: ✓ Air Conditioning: ✓ Electric Head: ✓
Heating: ✓ Hot Water: ✓ Refrigerator: ✓ Deep Freezer: ✓ Battery Charger: ✓ Outside Equipment Teak Cockpit: ✓ Teak Sidedecks:
✓ Cockpit Table: ✓ Swimming Ladder: ✓

INSPECTOR / HANDOVER SIGN-OFF

PREPARED BY

MotoComply ApS inspection team

FINAL HANDOVER CONFIRMATION

MotoComply ApS inspection report for Vehicle ID 14331. This report is generated from the current listing record and should be updated if listing data or inspection notes change.